


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD
DATE : 04.11.2022

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **YM9310G**
MODEL : **MITSUBISHI FM65FM1RDEA**
DATE OF ACCIDENT : 28.10.2022
TIME OF ACCIDENT : 20:40 HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE HOLDER <i>Dented</i>	1	\$ 856.00	\$ 856.00
2	TAIL LAMP <i>Not a</i>	2	\$ 245.30	\$ 490.60
3	TAIL LAMP SUPPORT BRACKET <i>Not a</i>	2	\$ 186.40	\$ 372.80
TOTAL PRICE				\$ 1,719.40
LESS 15% <i>25%</i>				\$ 257.91
SUB TOTAL PRICE				\$ 1,461.49

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 50.00	\$ 50.00
2	REAR BOX OPEN DOOR (SPECIAL TYPE) (COMPLETE SET) <i>Not a</i>	2	\$ 5,800.00	\$ 11,600.00
3	REAR BOX OPEN DOOR LOCK CATCH (SPECIAL TYPE) <i>Not a</i>	2	\$ 150.00	\$ 300.00
4	REAR BOX OPEN DOOR LOCK <i>Not a</i>	2	\$ 850.00	\$ 1,700.00
5	REAR BOX OPEN DOOR '60KM/H' <i>Not a</i>	1	\$ 30.00	\$ 30.00
9	REAR BOX OPEN DOOR FRAME (STANDARD STEEL) (SPECIAL TYPE)	1	\$ 6,800.00	\$ 6,800.00
10	REAR OPEN DOOR STICKER (SET) <i>Not a</i>	1	\$ 4,800.00	\$ 4,800.00

Rear Box Lower Beam *2800* *1400* TOTAL \$ 25,280.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,400.00	900
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,400.00	400

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **YM9310G**
MODEL : **MITSUBISHI FM65FM1RDEA**
DATE OF ACCIDENT : 28.10.2022
TIME OF ACCIDENT : 20:40 HRS

3	TRANSFER REAR DOOR MECHANISM	\$ 380.00	200
4	REAR CHASSIS ALIGNMENT	\$ 250.00	120
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 3,610.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,741.49
TOTAL LABOUR COST : \$ 3,610.00
TOTAL REPAIR COST : \$ 30,351.49

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian L

r/s 07/11/22 09

0/2 Days

total: 15172

y/s: 9.7K (Nett Value)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: