

Performance Motors

BMW Dealer



Supplementary

Estimate No. : **b1 63937**
Date Estimated : **07/11/2022**
Prepared By : **Foong Shiuh Jye**

Page No. :

- ESTIMATE REPAIR FOR -

Joshua Chew Shu Heng
Blk 402 Woodlands St 41
#06-134

Singapore 730402

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMH8511T	WBAJA12030BJ20879	12/02/2019	520i	19513

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To tow accident vehicle to PML workshop	150.00	0.00	150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# ADJUSTABLE BLIND RIVET	1.50	2.00	0.00	3.00 ✓
# HEX BOLT	1.55	4.00	0.00	6.20 ✓
# FRT RH SIDE PANEL BRACKET 1	42.45	1.00	0.00	42.45 ✓
# GRILLE AIR INLET MIDDLE (LINES)	101.75	1.00	0.00	101.75 ✓
# RH FOG LAMP SUPPORT	67.15	1.00	0.00	67.15 ✓
# RH BUMPER GUIDE	16.95	1.00	0.00	16.95 ✓
# FRAME BOTTOM	79.30	1.00	0.00	79.30 ✓
# COVER BULB REPLACEMENT	18.85	1.00	0.00	18.85 ✓
# RH COVER BOTTOM	76.05	1.00	0.00	76.05 ✓
# RH FOG LIGHT LED (BLENDE BLACK)	490.95	1.00	0.00	490.95 ✓

SUPPLEMENTARY ITEMS

Total Labour :	150.00
Total Parts :	902.65
Total Labour & Parts :	1,052.65

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

