

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3457H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,500.00	1,398.00
2	FRONT DISTANCE SENSOR (CENTRE) @\$280.00	NOT NECESSARY	560.00	-
4	FRONT DISTANCE SENSOR (OUTER) @\$260.00	NOT WORKING (1PC ONLY)	1,040.00	260.00
1	SET FRONT DISTANCE SENSOR WIRE	NOT NECESSARY	120.00	-
1	FRONT BUMPER HEADLAMP WASHER CAP	MISSING	105.00	105.00
1	FRONT LH HEADLAMP	CRACKED	2,880.00	1,566.25
1	FRONT LEFT HID HEADLAMP LIGHT BULB	NOT NECESSARY	180.00	-
1	HEADLAMP CONTROL MODULE BALLAST	DENTED	540.00	340.00
1	WASHER FLUID TANK	NOT NECESSARY	250.00	-
1	FRONT BUMPER SPONGE	CRACKED	168.00	168.00
	LESS 10% DISCOUNT		-734.30	-383.73
			6,608.70	3,453.52
	<u>LABOUR</u>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.		1,000.00	500.00
	SPRAY PAINTING.		750.00	600.00
	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS.		150.00	30.00
	WIRING / BULB CHECKING.		50.00	30.00
	REPLACE OF WASHER TANK.	NOT NECESSARY	200.00	-
	REMOVE & REFIX FRONT BUMPER REVERSE SENSOR.		100.00	30.00
	PROGRAMMING FOR HEADLAMP CONTROL MODULE BALLAST.		450.00	100.00
			2,700.00	1,290.00
	GRAND TOTAL		9,308.70	4,743.52

RECOMMENDED COST OF LUMP SUM REPAIRS		3,800.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. CS/INC22011180/Tqy3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.