



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: FIONA SHEN

Ref: CS/INC22011180/Tqy3e2

Date: 03/05/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMS 3857X	Veh. Inspected	SMP 3457H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1195980-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	08/11/2022

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2120472A095089	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	6 mm
L/H Front Tyre	225/45 R17	PIRELLI	6 mm
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/11/2022	Inspect Date / Time	08/11/2022 (04:40 PM)
Survey held at	8 Kaki Bukit Avenue 4 #03-41 Premier@Kaki Bukit		
Repairer	SAT (SG) PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**