

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 08 Nov 2022

Preliminary Advice

Vehicle No	: SNH4369C	Accident Date	: 01/11/2022
Make	: TOYOTA RAIZE	Policy No.	: MPC202200454CN
Assignment Date	: 08/11/2022	Excess	: S\$0.00
Date of Inspection	: 8/11/2022	Est. Duration of Repair	: 7
Inspection At	: Goldbell Engineering Pte Ltd		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,194.43
Revised Amount	:S\$	5,516.43
Check Items (Estimated)	:S\$	678.00
Total	:S\$	6,194.43

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	81,690.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,310.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .