



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: CS/CTI22011184/Kvp3

3 ANSON ROAD #16-00

Date: 09/11/2022

SPRINGLEAF TOWERSINGAPORE 079909

Code: CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	PC 9919K
Policy No.	DMB1SNW00015922200	Coverage (\$)	0.00
Claim No.	SNM22D208007/C01	Excess (\$)	2,000.00
Assign From	TAN KAH LEONG	Assign Date	08/11/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/11/2022	Inspection Date	08/11/2022
Survey held at	5035 ANG MO KIO INDUSTRIAL PARK 2, #01-367, ANG MO		
Repairer	GOLDBELL ENGINEERING PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.