

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 08 Nov 2022

**Preliminary Advice**

Vehicle No	: PC9919K	Accident Date	: 05/11/2022
Make	: TOYOTA HIACE	Policy No.	:
			DMB1SNW00015922200
Assignment Date	: 08/11/2022	Excess	: S\$2,000.00
Date of Inspection	: 8/11/2022	Est. Duration of Repair	: 18
Inspection At	: <b>Goldbell Engineering Pte Ltd</b>		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,437.37
Revised Amount	:S\$	20,402.37
Check Items (Estimated)	:S\$	14,825.00
Total	:S\$	35,227.37
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	28,000.00
COE / PARF Rebate	:S\$	1,309.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,691.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .