

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date: 20 / 07 / 2013

ESTIMATE COSTS OF REPAIR

M/s VS M&E Services Pte Ltd

C/o 160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

*Not wither
L/R @ 3100p
Heavy After Paint
4 days*

Dear Sir / Madam ,

Vehicle no. : GBH 4088 E - Toyota Dyna 150

Accident date : 04 / 11 / 2022

Quantity	Descriptions	Amount (S\$)
----------	--------------	----------------

1	1 pc	o/s tail gate 'L' bracket	\$	100.90	X
2	1 pc	o/s side gate	\$	1,341.20	✓
3	1 pc	o/s side bracket	\$	93.00	X
4	1 pc	o/s side bracket rubber	\$	31.20	X
5	1 pc	o/s rear wheel rim	\$	227.20	X
6	1 pc	fuel tank	\$	1,258.40	X
7	1 pc	fuel tank bracket	\$	387.30	X
8	1 pc	o/s rear mudflap	\$	62.70	X
9	1/2 pcs	rear wheel fender 1 @ 256.90	\$	513.80	✓
10	1 pc	o/s rear wheel rim hup bearing	\$	232.60	✓
11	1 pc	o/s rear wheel hup shaft	\$	867.00	✓
12	1 pc	o/s rear spring bar	\$	1,514.00	X
13	1 pc	o/s rear shock absorber	\$	189.60	X
14	1 pc	rear axle beam	\$	3,123.30	X
Less 25%			\$	9,942.20	
			\$	2,485.55	
			\$	7,456.65	
15	1 pc	o/s side gate guard	\$	850.00	sn X
16	1 pc	o/s side gate chrome guard	\$	650.00	sn X
17	1 pc	o/s rear wheel rim cap	\$	350.00	sn X
18	1 pc	o/s rear wheel tyre	\$	450.00	sn X
Balance C/FD			\$	9,756.65	

C 210

832

100 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (GBH 4088 E)	\$	9,756.65	
Labour charges	\$	2,200.00	500/
To putty and spray painting	\$	880.00	600/
Re-seal anti rust	\$	200.00	30/
To check, replace, repair wiring	\$	120.00	15/
Remove and refix fuel tank	\$	280.00	in X
Remove and refix rear undercarriage	\$	450.00	in X
To check wheel alignment	\$	80.00	60/
Plus : 7% GST	\$	13,966.65	
Sub-Total	\$	977.67	
	\$	14,944.32	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 08 / 11 / 2022

Tel : 6457 0678 Fax : 6457 8287
Co. and GST Reg. No. : 200820153N

RE : Supplementary

M/s VS M&E Services Pte Ltd
C/o 160 Sin Ming Drive
#05-09 Sin Ming Auto City
Singapore 575722

Dear Sir / Madam ,

Vehicle no. : GBH 4088 E - Toyota Dyna 150
Accident date : 04 / 11 / 2022

Quantity		Descriptions	Amount (S\$)	
1	1 pc	tools box (stainless steel) <i>PA</i>	\$ <i>Ad</i>	2,500.00 ✓ <i>700 Sn</i>
2	1 pc	rear exhaust pipe	\$ <i>R</i>	894.40 X
			\$	3,394.40
Less 25 %			\$	848.60
			\$	2,545.80
Remove and refix tools box			\$	350.00 <i>601</i>
			\$	2,895.80
Plus 7% GST			\$	202.71
Grand Total			\$	3,098.51