



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOH CYNTHIA		Ref: CS/ASM22011187/Kvp3e2 Date: 20/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 6843C	Veh. Inspected	GBH 4088E
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04E79	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	08/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFAT35Y90K210264	Colour	WHITE
Odometer	144431 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	KENDA	8 mm
L/H Front Tyre	195 R15X8	KENDA	8 mm
R/H Rear Tyre	155 R12X8 (D)	DUNLOP	5/5 mm
L/H Rear Tyre	155 R12X8 (D)	DUNLOP	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/11/2022	Inspection Date	08/11/2022
Survey held at	HC AUTO & MOTORS SERVICE BLK 14 SIN MING ESTATE, #01-07/09, SINGAPORE 575658		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	