



Supplementary

Estimate No. : **b1 63915**
 Date Estimated : **05/11/2022**
 Prepared By : **Han Kwan Yong**

Page No. :

- ESTIMATE REPAIR FOR -

Jong-Bin Wern Hwei
23 Canberra Drive
#05-48

Singapore 768077

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNF7240E	WBA7K120807K77611	17/06/2022	116i Hatch	3309

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

● * To replace rear windscreen glass Repeated	574.00	0.00	574.00 ✗
● * To conduct water leak tests Repeated	75.00	0.00	75.00 ✗
* To vacuum and clean car interior in order to retrieve all the possible shattered glass debris and shards caused by the accident (Nett Price)	250.00	0.00	250.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING NUT	2.85	2.00	0.00	5.70 ✓	NEC
# 3M S/F PREMIUM REAR WINDSCREEN	252.34	1.00	0.00	252.34 ✓	NEC

SUPPLEMENTARY ITEMS

Total Labour :	899.00
Total Parts :	258.04
Total Labour & Parts :	1,157.04

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

