

**Section A - Accident Details**

|                                    |                          |
|------------------------------------|--------------------------|
| Registration Number                | SHB551X                  |
| Case Reference Number              | TAX/11/22/2007           |
| Registration Date                  | 10/10/2017               |
| Company Type                       | Strides Taxi Pte Ltd     |
| Make                               | TOYOTA                   |
| Model                              | PRIUS4                   |
| Name of Driver                     | ABDUL SAMAD BIN MOHD ALI |
| Type of Accident                   | Side Swipe               |
| Accident Date and Time             | 4/11/2022 2:33 PM        |
| Accident Reported Date and Time    | 5/11/2022 10:09 AM       |
| Is Surveyor Required?              | Yes                      |
| Survey by                          |                          |
| Vehicle is Towed Back?             | No                       |
| Towed Back Date and Time           |                          |
| Replacement Vehicle issued?        | No                       |
| Job Card Number                    | 24116793                 |
| Special Instruction to ARC, if any | TP/ FRONT PORTION        |
| Prepared Date and Time             | 7/11/2022 1:01 PM        |
| Chassis Number                     |                          |
| Mileage                            |                          |
| Work Shop                          |                          |
| Repair Completion Date and Time    |                          |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                                                                            |                                                                                     |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                                                                         | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$676.00                                                                                                                                   | \$300.00                                                                            |
| Total Spray Cost             | \$558.00                                                                                                                                   | \$200.00                                                                            |
| Total Spare Part Cost        | \$12,246.24                                                                                                                                | \$4,166.93                                                                          |
| Total Other Cost             | \$380.00                                                                                                                                   | (\$916.93)                                                                          |
| <b>TOTAL COST</b>            | <b>\$13,860.24</b>                                                                                                                         | <b>\$3,750.00 (L/S)</b>                                                             |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                                                                              | <b>\$0.00</b>                                                                       |
| Number of Repair Days        | 5.0                                                                                                                                        | 3.0                                                                                 |
| Prepared / Adjusted By       | <b>Boon Chew Tay</b>                                                                                                                       | <b>RASUL (LKK) / NTUC</b>                                                           |
| ARC / Surveyor Sign Off Date | <b>07/11/2022 5:08 PM</b>                                                                                                                  | <b>07/11/2022 3:16 PM</b>                                                           |
| Signature                    |                                                         |  |
| Remarks                      | LUMP SUM REPAIR / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com |                                                                                     |

**Section C - Quotation and Accident Invoice Details**

|                         |              |                       |  |
|-------------------------|--------------|-----------------------|--|
| <b>Quotation Number</b> | QN-2212-0010 | <b>Invoice Number</b> |  |
| <b>Quotation Date</b>   | 06.12.2022   | <b>Invoice Date</b>   |  |
| <b>Invoice Amount</b>   |              | <b>Prepared Date</b>  |  |

**Section D - Details of Repair Estimates**

| <b>Part 1 - Labour Works</b> |                          |                                            |
|------------------------------|--------------------------|--------------------------------------------|
| <b>Job Scope</b>             | <b>Quotation from AR</b> | <b>Adjusted by Surveyor, if applicable</b> |
| TO REPAIR FRONT PORTION      | \$676.00                 | \$300.00                                   |
| <b>Total Labour</b>          | <b>\$676.00</b>          | <b>\$300.00</b>                            |

| <b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b> |                           |                                            |
|------------------------------------------------------------------|---------------------------|--------------------------------------------|
| <b>Job Scope</b>                                                 | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
| TO RESPRAY FRONT BUMPER                                          | \$378.00                  | \$200.00                                   |
| TO RESPRAY FRONT SUPPORT PANEL                                   | \$180.00                  | \$0.00                                     |
| <b>Total Spray Painting &amp; Panel Beating</b>                  | <b>\$558.00</b>           | <b>\$200.00</b>                            |

| <b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b> |                           |                                            |
|----------------------------------------------------------------------------|---------------------------|--------------------------------------------|
| <b>Job Scope</b>                                                           | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
| Lump Sum Adjustment by Surveyor                                            | \$0.00                    | (\$946.91)                                 |
| TO WASH AND VACUUM                                                         | \$60.00                   | \$0.00                                     |
| TO CHECK WIRING AND SYSTEM FUNCTION                                        | \$120.00                  | \$30.00                                    |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                    | \$100.00                  | \$0.00                                     |
| TO REPLACE SUNDRY PARTS                                                    | \$100.00                  | \$0.00                                     |
| <b>Total Other Costs</b>                                                   | <b>\$380.00</b>           | <b>(\$916.91)</b>                          |

| <b>Part 4 - Spare Parts / Material Usage</b> |                |                     |                           |                 |                        |                     |                         |                           |                          |
|----------------------------------------------|----------------|---------------------|---------------------------|-----------------|------------------------|---------------------|-------------------------|---------------------------|--------------------------|
| <b>Part Number</b>                           | <b>Portion</b> | <b>Stock Number</b> | <b>Part Name</b>          | <b>Quantity</b> | <b>List Price (\$)</b> | <b>Discount (%)</b> | <b>Final Price (\$)</b> | <b>Estimator Approved</b> | <b>Surveyor Approved</b> |
|                                              |                | 5211947962          | COVER, FR BUMPER          | 1.00            | \$560.30               | 25.00               | \$420.23                | Replace                   | Replace                  |
|                                              |                | 5211547050          | SUPPORT, FR BUMPER RH     | 0.00            | \$86.20                | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5211647050          | SUPPORT, FR BUMPER LH     | 0.00            | \$86.20                | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5211447190          | BRACKET, FR BUMPER        | 1.00            | \$111.80               | 25.00               | \$83.85                 | Replace                   | Replace                  |
|                                              |                |                     | NUMBER PLATE              | 1.00            | \$35.00                | 0.00                | \$35.00                 | Replace                   | Replace                  |
|                                              |                |                     | NUMBER PLATE FRAME        | 1.00            | \$25.00                | 0.00                | \$25.00                 | Replace                   | Replace                  |
|                                              |                | 5202147110          | REINFORCEMENT FRONT UPPER | 1.00            | \$773.90               | 25.00               | \$580.43                | Replace                   | Replace                  |
|                                              |                | 5261147140          | ABSORBER, FR BUMPER       | 1.00            | \$85.90                | 25.00               | \$64.43                 | Replace                   | Replace                  |
|                                              |                | 5210347010          | EXTENSION SUB-ASSY, LH    | 0.00            | \$129.90               | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5210247020          | EXTENSION SUB-ASSY, RH    | 0.00            | \$129.90               | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5213247010          | REINFORCEMENT FRONT LOWER | 0.00            | \$265.90               | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5261847090          | ABSORBER, FR BUMPER LOWER | 0.00            | \$143.60               | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 5339547040          | SEAL, HOOD TO FR END      | 0.00            | \$55.80                | 0.00                | \$0.00                  | Replace                   | Not Given                |
|                                              |                | 7531047060          | EMBLEM ASSY FRONT         | 1.00            | \$98.70                | 25.00               | \$74.03                 | Replace                   | Replace                  |

✓ scr  
 X nn  
 X nn  
 ✓ cra  
 ✓ bt  
 ✓ cut  
 ✓ bt  
 ✓ cra  
 X nn  
 X nn  
 X nn  
 X nn  
 X nn  
 ✓ nec

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |  |
|---------------------------------------------------|--|
| <b>STRIDES Automotive Services Pte Ltd</b>        |  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |  |
| FAX Number : 63685592                             |  |
| Estimator Telephone Number : 68662623             |  |
| Accident Reporting Number : 68662672              |  |

Date Generated : 12/12/2022

User ID : LauSW

|              |  |            |                                      |       |                    |       |                   |         |           |      |
|--------------|--|------------|--------------------------------------|-------|--------------------|-------|-------------------|---------|-----------|------|
|              |  | 5311247240 | GRILLE, RADIATOR                     | 0.00  | \$183.90           | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5310147080 | GRILLE SUB-ASSY                      | 1.00  | \$374.40           | 25.00 | \$280.80          | Replace | Replace   | √cra |
|              |  | 5216116010 | CLIPS PIECE, FRT & RR BUMPER         | 10.00 | \$4.80             | 25.00 | \$36.00           | Replace | Replace   | √nec |
|              |  | 5253550060 | RETAINER, FR BUMPER, LH & RH         | 0.00  | \$9.50             | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5142047030 | COVER ASSY, ENGINE                   | 0.00  | \$201.00           | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5141047020 | COVER ASSY, ENGINE UNDER CENTER SET  | 0.00  | \$511.20           | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 8114547691 | UNIT , HEADLAMP , RH                 | 0.00  | \$2,852.40         | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 8118547691 | UNIT , HEADLAMP , LH                 | 1.00  | \$2,852.40         | 10.00 | \$2,567.16        | Replace | Replace   | √cra |
|              |  | 8122047020 | LAMP ASSY, FOG, LH                   | 0.00  | \$1,029.90         | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 8121047020 | LAMP ASSY, FOG, RH                   | 0.00  | \$1,029.90         | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 8105647690 | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 | 0.00  | \$1,039.90         | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5320547900 | SUPPORT S/A UPPER,                   | 0.00  | \$408.50           | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5321447050 | SUPPORT, RADIATOR UPPER LH           | 0.00  | \$85.20            | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 5321347050 | SUPPORT, RADIATOR UPPER RH           | 0.00  | \$85.20            | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
|              |  | 8101647690 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 | 0.00  | \$1,039.90         | 0.00  | \$0.00            | Replace | Not Given | Xnn  |
| <b>Total</b> |  |            |                                      |       | <b>\$14,296.20</b> |       | <b>\$4,166.93</b> |         |           |      |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|--------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| <b>Total</b> |         |              |           |          |               |              |                  |           |                |

|   |                 |               |
|---|-----------------|---------------|
|   | 4,166.93        |               |
| + | 300.00          | L/S \$3,750/- |
| + | 230.00          |               |
|   | <u>4,696.93</u> |               |
|   | -20%            |               |
|   | <u>3,757.54</u> |               |