

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SMY9031R
Chassis No: MNTFEAP15Z0000893
Engine No: HR12361259C

Report No : 202211-02
Date : 11.11.2022

Replacement of Damaged Parts

<u>S/No.</u>	<u>QTY</u>	<u>Description</u>	<u>Condition / Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
1	1	Front RH Door	Damaged	\$ 1,212.00	\$ 1,090.80
2	1	Rear RH Door	Damaged	\$ 1,212.00	\$ 1,090.80
3	1	Rear RH Fender	Scratches	\$ 895.00	\$ 805.50
4	1	RH Side Skirt	Damaged	\$ 667.00	\$ 600.30
5	1	Rear RH Mud Flap Trim	Necessary	\$ 225.00	\$ 202.50
6	1	Rear RH Rim	Damaged	\$ 1,250.00	\$ 1,125.00
7	1	Front RH Door Garnish	Scratches	\$ 346.00	\$ 311.40
8	1	Rear RH Door Garnish	Scratches	\$ 346.00	\$ 311.40
				\$ 6,768.30	\$ 6,091.47

Total (Parts): \$ 6,768.30 -10% \$ 6,091.47

Labour Charges

26	To fix & dismantle and remove damaged Front Portions; affected damaged portion.	\$ 1,000.00
27	To apply anti rust coat and affected areas	\$ 120.00
28	To check wiring	\$ 180.00
29	Welding and cutting of affected panels, including chassis alignme	\$ 800.00
30	Spray painting for Front Portions affected parts	\$ 1,000.00
31	Refocusing of the front headlamp	\$ -
32	Diagnose ECU system and reset error code.	\$ -
33	3D Wheel Alignment	\$ 120.00
34	To Apply Waterproofing sealer on Front Support Panels	\$ 180.00
Total Labour:		\$ 3,400.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 9,491.47

Less 20% \$ 7,593.18