



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:TEE LEE GREEN			Ref: CC4/ASM22011196/Rpa3q2 Date: 09/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6783T	Veh. Inspected	SLH 8760C
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04E7U	Excess (\$)	0.00
	Assign From		Assign Date	08/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5 DX CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHMRU1810GX201229	Colour	BLUE
	Odometer	165012 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/11/2022	Inspection Date	09/11/2022
	Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	