



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM22011198/Apa3q2 Date: 20/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6741P	Veh. Inspected	SBW 91S
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04E71	Excess (\$)	0.00
	Assign From		Assign Date	07/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLS350 COUPE	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WDD2573502A050455	Colour	BLACK
	Odometer	36361 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/35 R19	PIRELLI	6 mm
	L/H Front Tyre	275/35 R19	PIRELLI	6 mm
	R/H Rear Tyre	275/35 R19	PIRELLI	6 mm
	L/H Rear Tyre	275/35 R19	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/11/2022	Inspection Date	08/11/2022
	Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	