



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|---|--|-----------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA | | | Ref: CC4/ASM22011199/Kpa3q2 Date: 30/12/2022 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SDY 5353U | Veh. Inspected | SMA 8553J |
| | Policy No. | GA559273 | Coverage (\$) | 0.00 |
| | Claim No. | S2M04EBY | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 09/11/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA SIENTA (A) | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | NHP1707126227 | Colour | METALLIC SILVER |
| | Odometer | 72572 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 185/60 R15 | YOKOHAMA | 8 mm |
| | L/H Front Tyre | 185/60 R15 | YOKOHAMA | 8 mm |
| | R/H Rear Tyre | 185/60 R15 | YOKOHAMA | 8 mm |
| | L/H Rear Tyre | 185/60 R15 | YOKOHAMA | 8 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 07/11/2022 | Inspection Date | 09/11/2022 |
| | Survey held at | GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721 | | |
| 5a. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |