

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SMA8553J

No.	Qty	List Items			
1	1	Rear bumper	\$ R	768.40	X
2	1	Rear bumper centre black garnish <i>295.50</i>	\$ M	332.40	✓
3	2	Rear bumper side black garnish	\$ Pm	258.20	X
4	2	Rear bumper corner retainer (Below taillamp)	\$ Pm	138.70	X
5	2	Rear bumper side retainer	\$ Pm	136.20	X
6	1 set	Rear bumper clips	\$ Nm	40.00	X
7	1	Rear tailgate <i>1320</i>	\$ Pm	1,320.00	✓
8	1	Rear tailgate top "TOYOTA" logo	\$ Nm	74.20	—
9	1	Rear tailgate RH "HYBRID" emblem	\$ Nm	52.30	—
10	1	Rear tailgate weatherstrip <i>288.90</i>	\$ Gt	329.10	—
11	1 set	Rear tailgate inner trim board clips	\$ Nm	60.00	X
12	1	Rear tailgate top lock <i>387.90</i>	\$ Pm	509.10	✓
13	1	Rear end panel	\$ R	682.30	X
14	1	Rear end panel inner keyless sensor	\$ Sm	226.30	X
			\$	4,927.20	
			Less 25%	\$ 1,231.80	
			Total :	\$ 3,695.40	

Special Nett Items

15	1 set	Rear windscreen sealant	\$ Nm	80.00	401m
16	1 set	Rear end panel sealant	\$ Nm	80.00	X
17	1 set	Reverse sensor	\$ Sch	250.00	200sm
			Total :	\$ 410.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	450l
2	To putty and spray Spray Paintings charges.	\$	1,000.00	400.
3	To remove, refit rear windscreen glass.	\$	140.00	120l
4	To check wirings and lightings.	\$	40.00	15l
5	To remove, refit rear tailgate fittings.	\$	80.00	60l
6	To remove, refix reverse sensors & reverse camera.	\$	150.00	80l
7	To remove, refit rear upholstery and attachments.	\$	120.00	X
8	To supply and apply anti rust treatment	\$	90.00	30l
	Total :	\$	2,620.00	

Total Parts and Labour : \$ 6,725.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: