

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 27 Mar 2023

Preliminary Advice

Insured Vehicle No	: YL7830R	Accident Date	: 04/11/2022
TP Vehicle No	: SHD3614T	Assignment Date	: 09/11/2022
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 7
Date of Inspection	: 09/11/2022		
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,335.42
Revised Amount	:S\$	17,816.31
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,816.31
 Lump Sum Repair	 :S\$	 14,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.