

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD215G****AAD2211-034**

*Not Notarized*  
*11 Pm @ 4300h Max*  
*Recovery After Pain*

Vehicle No.:  
 Chassis No.:  
 UEN No:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

**09 NOV 2022****SHD215G**

VF1ABL15AUC281586

200303878K

RENAULT

LATITUDE

04/11/2022

**GBC9673J/FCI**

02/10/2015

| PART                               | LIST                |
|------------------------------------|---------------------|
| 1 BUMPER COVER REAR                | \$ Bu 561.70 —      |
| 1 BUMPER LOWER REAR                | \$ Bu 411.90 —      |
| 1 BUMPER BRACKET CTR REAR          | \$ D11 98.10 —      |
| 1 BUMPER BRACKET SIDE RH REAR      | \$ D11 82.10 —      |
| 1 BUMPER RETAINER RH REAR          | \$ R 59.80 X        |
| 1 BUMPER BRACKET SIDE LH REAR      | \$ R 80.80 X        |
| 1 BUMPER RETAINER LH REAR          | \$ D11 54.20 —      |
| 1 BUMPER BEAM REAR                 | \$ B1 547.80 —      |
| 1 OUTER PANEL REAR (End Panel)     | \$ B1 745.80 —      |
| 1 OUTER PANEL REAR (End Panel)TRIM | \$ D11 404.56 —     |
| 1 BOOT REAR                        | \$ B1 1,677.20 —    |
| 1 BOOT LOCK                        | \$ R 246.60 X       |
| 1 BOOT LOCK CATCH                  | \$ R 41.70 X        |
| 1 BOOT FINISHER                    | \$ R 344.70 X       |
| 1 BOOT WEATHERSTRIP                | \$ G1 178.20 508.50 |
| 1 BOOT STRUT LH                    | \$ R 145.10 X       |
| 1 BOOT STRUT RH                    | \$ R 145.10 X       |
| 1 BOOT HINGE LH                    | \$ R 254.20 X       |
| 1 BOOT HINGE RH                    | \$ R 254.20 X       |
| 1 BOOT BADGE 'RENAULT'             | \$ MC 82.40 —       |
| 1 BOOT BADGE                       | \$ R 95.80 —        |
|                                    | <b>\$ 6,511.96</b>  |
| 10%                                | <b>\$ 1,007.88</b>  |
|                                    | <b>\$ 9,070.88</b>  |

**Special Nett**

**Trans-cab Auto Services Pte Ltd**

AAD2211-034

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD215G**

|                                     |           |                  |        |
|-------------------------------------|-----------|------------------|--------|
| 1SET PARKING AID                    | \$        | phon 700.00      | 400.00 |
| 1SET REAR BUMPER CLIP               | \$        | nn 66.00         | ✓      |
| 1SET BUMPER BRACKET SIDE CLIP RH RR | \$        | nn 10.00         | X      |
| 1SET BUMPER RETAINER RH CLIP RR     | \$        | nn 20.00         | X      |
| 1SET BUMPER BRACKET SIDE CLIP LH RR | \$        | nn 10.00         | X      |
| 1SET BUMPER RETAINER CLIP LH RR     | \$        | nn 20.00         | X      |
| 1SET BUMPER LOWER REAR CLIP         | \$        | nn 66.00         | ✓      |
| 1 REAR BOOT STICKER 'Trans-cab'     | \$        | nn 80.00         | 30.00  |
| 1 REAR BOOT STICKER '6555-3333'     | \$        | nn 80.00         | 30.00  |
| 1 LICENSE PLATE WITH HOLDER REAR    | \$        | nn 120.00        | 45.00  |
| 2 WINDSCREEN SEALANT                | \$        | nn 150.00        | X      |
| 1 WINDSCREEN MOULDING               | \$        | nn 200.00        | X      |
| 1 WINDSCREEN INNER SPONGE SEAL      | \$        | nn 130.00        | X      |
| <b>TOTAL</b>                        | <b>\$</b> | <b>1,752.00</b>  |        |
| <b>TOTAL PARTS</b>                  | <b>\$</b> | <b>10,822.88</b> |        |

**LABOUR**

|                                                                                                                           |    |           |        |
|---------------------------------------------------------------------------------------------------------------------------|----|-----------|--------|
| To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.                                      | \$ | nn 300.00 | X      |
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 3,000.00  | 660.00 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 3,000.00  | 660.00 |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00    | 60.00  |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00    | 60.00  |
| To transfer of bootlid fittings, attachments and perform water seepage test.                                              | \$ | 170.00    | 60.00  |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | nn 170.00 | X      |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | nn 170.00 | X      |

**Trans-cab Auto Services Pte Ltd****AAD2211-034**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD215G**

To transfer of rear end panel fittings, attachment and  
perform water seepage test. \$ 170.00 601

To transfer of rear windscreen fittings and conduct  
water seepage test. \$ ~ 170.00 X

To check steering geometry and computer wheel  
alignment \$ ~ 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 201

**TOTAL \$ 7,880.00**

**Over All Total \$ 27,773.77**

**(LUMP SUM)**

**Repair Days 05 DAYS**

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: