

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAN		Ref:	CS3/AIS22011206/y3		
	79 ROBINSON RO #09-01 SINGAPOR			Date:	09/11/2022	
				Code:	AIS	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMU 6546M	Veh. Inspected	k	SJZ 8555H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22007948/KC	Excess (\$)		0.00	
	Assign From	JANICE KOH	Assign Date		08/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	06/11/2022	Inspection Dat	e	10/11/2022	
	Survey held at	HARMONY MOTOR (AMK) PTE LTD				
		BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT SINGAPORE 568047				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					