

Not Withheld
Returning B4 paint

AAD2211-010

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 NOV 2022

SHC5721J

JTDKB3FU603092471

TOYOTA

PRIUS GEN 4

31/10/2022

SLS8950M/ Tokyo

13/09/2021

PART

LIST

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH
- 1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, RH
- 1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 RIM
- 1 HUBCAP
- 1 FENDER SUB-ASSY, FRONT RH
- 1 EMBLEM, SIDE PANEL, RH
- 1 LINER, FRONT FENDER, LH
- 1 COVER, FRONT BUMPER
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 BRACKET, FRONT BUMPER SIDE, RH

\$	13	1,300.70	
\$	13	193.50	
\$	13	390.60	
\$	13	926.00	
\$	13	321.10	
\$	13	110.60	
\$	13	97.50	
\$	13	238.30	
\$	13	43.50	
\$	13	13.30	
\$	13	26.30	
\$	13	1,436.60	
\$	13	1,900.10	
\$	13	211.50	
\$	13	977.80	✓
\$	13	54.60	✓
\$	13	210.30	✓
\$	13	521.00	✓
\$	13	47.50	X
\$	13	59.30	X

TOTAL \$ 9,080.10

25% \$ 2,270.03

\$ 6,810.08

Special Nett

- 1 FRT FENDER LINER CLIP

\$ 13 65.00 ✓

Trans-cab Auto Services Pte Ltd

AAD2211-010

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

1 FRT BUMPEPER CLIP	\$	nn 65.00	605A
1 DOOR STICKER TRANSCAB	\$	nn 100.00	605A
1 DOOR TRIM CLIP	\$	nn 75.00	X
1 DOOR WEATHERSTRIP CLIP	\$	nn 80.00	X
TOTAL	\$	385.00	
TOTAL PARTS	\$	7,195.08	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	8001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	6601
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	151
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd

AAD2211-010

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

TOTAL	\$	5,100.00
--------------	-----------	-----------------

Over All Total	\$	12,295.08
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

__ Days

3 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: