

Not Authorized
Permy B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

AAD2211-010

2612.78

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 NOV 2022

SHC5721J

JTDKB3FU603092471

TOYOTA

PRIUS GEN 4

31/10/2022

SLS8950M/ Tokyo

13/09/2021

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,300.70
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	193.50
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	390.60
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	926.00
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	321.10
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	1,436.60
1	RIM	\$	1,900.10
1	HUBCAP	\$	211.50
1	FENDER SUB-ASSY, FRONT RH	\$	977.80
1	EMBLEM, SIDE PANEL, RH	\$	54.60
1	LINER, FRONT FENDER, LH	\$	210.30
1	COVER, FRONT BUMPER	\$	521.00
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50
1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30
TOTAL		\$	9,080.10
25%		\$	2,270.03
		\$	6,810.08

Special Nett

1 FRT FENDER LINER CLIP \$ 65.00

Trans-cab Auto Services Pte Ltd**AAD2211-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

1	FRT BUMPEPER CLIP	\$	<i>na</i> 65.00	<i>60sa</i>
1	DOOR STICKER TRANSCAB	\$	<i>na</i> 100.00	<i>60sa</i>
1	DOOR TRIM CLIP	\$	<i>na</i> 75.00	<i>X</i>
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i> 80.00	<i>X</i>
TOTAL		\$	385.00	
TOTAL PARTS		\$	7,195.08	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>4001</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>6601</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2211-010**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5721J

TOTAL	\$	5,100.00
--------------	-----------	-----------------

Over All Total	\$	12,295.08
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days**— Days***3 days*

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: