

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0962/2022/EQ
DATE : 3-Nov-22
WIP : 48929

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR YEO YING PENG (YANG YINGPING)
ADDRESS : 27 JALAN ANGGEREK
SINGAPORE 369462

TELEPHONE : HP +65 92260118
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100472838-06
VEHICLE NO : **SLH 810 U**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TF
MODEL YEAR : 29/6/2016
ENGINE NO : CZC 551007
CHASSIS NO : WAUZZZ8V0GA155389
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Nov-22
PLACE OF ACCIDENT : T-JUNCTION OF SIANG KUANG AVENUE
AND JALAN WANGI

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLH 810 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	900.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	\$	900.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 2,702.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 810 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>del d</i>	<i>cracked</i> 1	\$ 2,146.00	✓ 1716.80
2	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>del d</i>	1	\$ 175.00	+ 139.60
3	FRONT BUMPER PULL STRAP - LOWER <i>del d</i>	4	\$ 231.00	+
4	FRONT BUMPER GUIDE SECTION - RH <i>del d</i>	1	\$ 71.00	+
5	FRONT BUMPER AIR GUIDE GRILLE - RH <i>del d</i>	1	\$ 122.00	+
6	RADIATOR GRILLE <i>del d</i>	1	\$ 765.00	✓ 612
7	RADIATOR GRILLE COVER <i>nn</i>	1	\$ 109.00	? x
8	CAUTION SIGN STICKER <i>del d</i>	1	\$ 16.00	✓ 12.40
9	AIR CONDITIONER STICKER <i>del d</i>	1	\$ 9.00	✓ 6.64
10	FRONT BUMPER REINFORCEMENT BEAM <i>del d</i>	1	\$ 847.00	+
11	FRONT BUMPER FOAM FILLER PIECE <i>del d</i>	1	\$ 93.00	+
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>nn</i>	1	\$ 63.00	? x
13	HORN SIGNAL HIGH TONE - RH <i>del d</i>	1	\$ 213.00	+
14	FRONT WHEEL HOUSING LINER - RH <i>del d</i>	1	\$ 183.00	+
15	HEADLIGHT - RH <i>del d</i>	1	\$ 2,810.00	+
16	LIFT CYLINDER - RH <i>del d</i>	1	\$ 211.00	+
17	LIFT CYLINDER HOSE <i>del d</i>	1	\$ 204.00	+
18	OUTSIDE TEMPERATURE SENSOR BRACKET <i>del d</i>	1	\$ 21.00	+
19	RADIATOR AIR GUIDE - RH <i>del d</i>	1	\$ 28.00	+
20	RADIATOR AIR GUIDE SEAL - RH OUTER <i>del d</i>	1	\$ 9.00	+
SUB TOTAL SPARE PARTS		:	\$ 8,326.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLH 810 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	RADIATOR AIR GUIDE - UPPER CENTRE <i>Ken</i>	1	\$ 14.00	<i>+</i>	
22	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i> 60	
23	SUNDRIES <i>nn</i>		\$ 400.00	<i>?</i> x	
TOTAL SPARE PARTS		:	\$ 8,800.00		
TOTAL LABOUR CHARGES		:	\$ 2,702.00		
GRAND TOTAL		:	\$ 11,502.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *08/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT