

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0970/2022/EQ
DATE : 7-Nov-22
WIP : 49294

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS CHEE SIANG KEOW
ADDRESS : 84 JALAN LOKAM
SINGAPORE 537909

TELEPHONE : HP +65 92767330
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SLR 3043 U**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 8/8/2017
ENGINE NO : CHZ 399389
CHASSIS NO : WAUZZZ8V6J1003544
MILEAGE : 118,852
DATE IN : 5-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Nov-22
PLACE OF ACCIDENT : JALAN BESAR ROAD > BENCOOLEN STREET
(RIGHT BEFORE SIM LIM SQUARE)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 3043 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 3043 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,432.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 195.00	+	
3	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 43.00	✓	
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 179.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 571.00	+	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 318.00	+	
7	FRONT BUMPER TRIM COVER - LH <i>?</i>	1	\$ 182.00	?	
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	1	\$ 42.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 210.00	+	
10	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 847.00	+	
11	FRONT BUMPER REINFORCEMENT BEAM COVER <i>new</i>	1	\$ 136.00	+	
12	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 211.00	?	
13	AIR CONDITIONER STICKER <i>new</i>	1	\$ 9.00	+	
14	CAUTION SIGN STICKER <i>new</i>	1	\$ 16.00	+	
15	HORN HIGH TONE - LH <i>new</i>	1	\$ 213.00	+	
16	FRONT FENDER - LH <i>Distorted</i>	1	\$ 954.00	✓	
17	FRONT FENDER RIVET <i>new</i>	5	\$ 19.00	✓	
18	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 75.00	+	
19	FRONT FENDER BRACKET - LH <i>?</i>	1	\$ 46.00	?	
20	FRONT FENDER BRACE <i>?</i>	1	\$ 107.00	?	
SUB TOTAL SPARE PARTS		:	\$ 6,805.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 3043 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 183.00	+	
22	HEADLIGHT - LH <i>crack</i>	1	\$ 5,879.00	✓	
23	HEADLIGHT POWER MODULE - LH <i>new</i>	1	\$ 850.00	+	
24	HEADLIGHT CONTROL UNIT <i>new</i>	1	\$ 625.00	+	
25	HEADLIGHT HEAT SINK - LH <i>new</i>	1	\$ 818.00	+	
26	HEADLIGHT HOSE - LH	1	\$ 46.00	+	
27	LIFT CYLINDER <i>new</i>	1	\$ 156.00	+	
28	LIFT CYLINDER HOSE	1	\$ 78.00	+	
29	LIFT CYLINDER WASH WATER RESERVOIR <i>new</i>	1	\$ 226.00	+	
30	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	+	
31	RADIATOR AIR GUIDE - LH <i>new</i>	1	\$ 28.00	+	
32	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	1	\$ 14.00	+	
33	SUNDRIES		\$ 400.00	?	
TOTAL SPARE PARTS		:	\$ 16,129.00		
TOTAL LABOUR CHARGES		:	\$ 5,002.00		
GRAND TOTAL		:	\$ 21,131.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lj
08/11/22

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

