

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0974/2022/EQ
DATE : 8-Nov-22
WIP : 49485

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
8 days - ok - Johnny Boo
18-Jan-23*

OWNER'S NAME : MR ROLAND SCHWINN
ADDRESS : 10 GOPENG STREET
#32-14
SINGAPORE 078878
TELEPHONE : HP +65 91991254
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210011404-01
VEHICLE NO : **SMX 7901 Z**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29/1/2021
ENGINE NO : CZD C22632
CHASSIS NO : WAUZZZF36M1057657
MILEAGE : 8,811
DATE IN : 7-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Nov-22
PLACE OF ACCIDENT : COMMONWEALTH AVE/QUEENSWAY JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7901 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$ 250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,600.00	\$ 1,600.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	\$ 1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	\$ 3,000.00
TOTAL LABOUR CHARGES		:	\$ 10,480.00	\$ 6,530.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7901 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		\$ 6,530.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS.	\$	4,500.00	\$ 1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 15,172.00	\$ 8,372.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,308.00	\$	1,846.00
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 132.00		
3	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	\$	193.60
4	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$ 58.00		
5	FRONT BUMPER GRILLE - LH / RH	2	\$ 248.00		
6	FRONT BUMPER END PLATE	1	\$ 212.00		
7	FRONT BUMPER SPOILER	1	\$ 426.00	\$	340.80
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 342.00	\$	136.40
9	RADIATOR GRILLE	1	\$ 1,594.00	\$	1,275.20
10	RADIATOR GRILLE STRIKER PLATE	1	\$ 271.00	\$	216.80
11	RADIATOR GRILLE COVER CAP	1	\$ 47.00	\$	36.88
12	RADIATOR GRILLE BRACKET	1	\$ 46.00		
13	RADIATOR GRILLE SECURING PLATE	1	\$ 37.00		
14	FRONT "360" CAMERA	1	\$ 1,264.00		
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00	\$	91.20
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	\$	778.80
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 86.00		
18	FRONT BUMPER TOP COVER	1	\$ 137.00	\$	109.60
19	CAUTION SIGN STICKER	1	\$ 16.00	\$	12.40
20	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
SUB TOTAL SPARE PARTS		:	\$ 8,563.00	\$	5,044.32

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	5,044.32
21	FRONT PARKING AID SENSOR - INNER / OUTER	3	\$ 797.00		
22	FRONT PARKING AID SEAL RING	4	\$ 10.00		
23	FRONT BUMPER WIRING SET	1	\$ 750.00	\$	600.00
24	HORN HIGH TONE - LH	1	\$ 154.00		
25	HORN LOW TONE - RH	1	\$ 146.00		
26	HORN BRACKET - LH / RH	2	\$ 50.00		
27	FRONT FENDER - LH / RH	2	\$ 2,890.00	\$	1,156.00
28	FRONT FENDER BRACE - LH / RH	2	\$ 196.00		
29	FRONT FENDER BRACKET - LH / RH	2	\$ 78.00		
30	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 520.00		
31	FRONT WHEEL HOUSING LINER COVER - LH / RH	2	\$ 36.00		
32	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH / RH	2	\$ 44.00		
33	BONNET	1	\$ 3,695.00	\$	2,956.00
34	BONNET HINGE - LH / RH	2	\$ 162.00	\$	128.96
35	BONNET ATTACHMENT PARTS	1	\$ 309.00		
36	BONNET STRIKER - LH / RH	2	\$ 246.00		
37	BONNET IMPACT PROTECTION - CENTER	1	\$ 31.00	\$	24.24
38	BONNET LOCK - LH / RH	2	\$ 455.00		
39	BONNET SOUND ABSORBER	1	\$ 244.00		
40	BONNET RELEASE ELEMENT	1	\$ 65.00		
SUB TOTAL SPARE PARTS		:	\$ 10,878.00	\$	9,909.52

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>C/F</i>		<i>\$</i>	<i>9,909.52</i>
41	BONNET RELEASE LEVER	1	\$ 16.00		
42	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00		
43	BONNET BOWDEN CABLE COVER	1	\$ 11.00		
44	BONNET LOCK CABLE	1	\$ 82.00		
45	BONNET LOCK CABLE COVER - LH / RH	2	\$ 92.00		
46	PLENUM CHAMBER COVER	1	\$ 144.00		
47	HEADLIGHT MOUNTING - LH / RH	2	\$ 264.00	<i>\$</i>	<i>210.40</i>
48	HEADLIGHT - LH / RH	2	\$ 11,904.00	<i>\$</i>	<i>4,761.60</i>
49	HEADLIGHT HEAT SINK	1	\$ 870.00		
50	HEADLIGHT POWER MODULE	1	\$ 850.00		
51	HEADLIGHT HOSE - LH	1	\$ 28.00		
52	LIFT CYLINDER - LH / RH	2	\$ 462.00	<i>\$</i>	<i>184.40</i>
53	LIFT CYLINDER HOSE	1	\$ 92.00		
54	LIFT CYLINDER WASH WATER RESERVOIR	1	\$ 240.00		
55	LOCK CARRIER	1	\$ 1,412.00	<i>\$</i>	<i>1,129.60</i>
56	A/C CONDENSER	1	\$ 605.00	<i>\$</i>	<i>483.60</i>
57	RADIATOR ADDITIONAL COOLER	1	\$ 984.00	<i>\$</i>	<i>786.80</i>
58	RADIATOR	1	\$ 1,093.00		
59	READY-MIX COOLANT	6	\$ 297.00	<i>\$</i>	<i>237.12</i>
60	RADIATOR AIR GUIDE - LH / RH	2	\$ 86.00	<i>\$</i>	<i>34.08</i>
SUB TOTAL SPARE PARTS		:	\$ 19,596.00	<i>\$</i>	<i>17,737.12</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 17,737.12
61	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 96.00	\$ 37.84
62	AIR INTAKE COVER - UPPER	1	\$ 64.00	
63	AIR INTAKE COVER - LOWER	1	\$ 59.00	
64	AIR INTAKE COVER - CENTER	1	\$ 21.00	
65	FRONT WHEEL COVER - LH / RH	2	\$ 566.00	\$ 452.00
66	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
67	SUNDRIES		\$ 400.00	\$ 74.72
TOTAL SPARE PARTS			\$ 40,303.00	\$ 18,361.68
TOTAL LABOUR CHARGES			\$ 15,172.00	\$ 8,372.00
GRAND TOTAL			\$ 55,475.00	\$ 26,733.68

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-15/12/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT