

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0974/2022/EQ
DATE : 8-Nov-22
WIP : 49485

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING


SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ROLAND SCHWINN
ADDRESS : 10 GOPENG STREET
#32-14
SINGAPORE 078878
TELEPHONE : HP +65 91991254
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210011404-01
VEHICLE NO : SMX 7901 Z
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29/1/2021
ENGINE NO : CZD C22632
CHASSIS NO : WAUZZZF36M1057657
MILEAGE : 8,811
DATE IN : 7-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Nov-22
PLACE OF ACCIDENT : COMMONWEALTH AVE/QUEENSWAY JUNCTION

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7901 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ 480
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250 250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00	✓ 1600
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓ (Pricing) 1200
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	2500. 2500 3000
TOTAL LABOUR CHARGES		\$ 10,480.00	

 PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 7901 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS.	\$ 4,500.00	1100 1100 1650
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ 192
TOTAL LABOUR CHARGES		: \$ 15,172.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delud</i>	1 S	2,308.00 ✓	1846
2	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 S	132.00 +	
3	FRONT BUMPER GRILLE - CENTER <i>could ✓</i>	1 S	242.00 +	193.6 con <i>sls</i>
4	FRONT BUMPER LOWER GRILLE COVER PLATE <i>the new</i>	1 S	58.00 ? x	
5	FRONT BUMPER GRILLE - LH / RH <i>new</i>	2 S	248.00 +	
6	FRONT BUMPER END PLATE <i>new</i>	1 S	212.00 +	
7	FRONT BUMPER SPOILER <i>cut ✓</i>	1 S	426.00 +	340.8 con <i>sls</i>
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>✓ could</i>	2 S	342.00 +	136.4 con <i>sls</i>
9	RADIATOR GRILLE <i>could</i>	1 S	1,594.00 ✓	1275.2
10	RADIATOR GRILLE STRIKER PLATE <i>could</i>	1 S	271.00 ✓	216.8
11	RADIATOR GRILLE COVER CAP <i>could ✓</i>	1 S	47.00 +	36.88 con <i>sls</i>
12	RADIATOR GRILLE BRACKET <i>? x } new</i>	1 S	46.00 ? x	
13	RADIATOR GRILLE SECURING PLATE <i>? x</i>	1 S	37.00 ? x	
14	FRONT "360" CAMERA <i>new</i>	1 S	1,264.00 x	
15	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1 S	114.00 ✓	91.2
16	FRONT BUMPER REINFORCEMENT BEAM <i>Delud</i>	1 S	974.00 ✓	778.8
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>? x new</i>	2 S	86.00 ? x	
18	FRONT BUMPER TOP COVER <i>Delud</i>	1 S	137.00 ✓	109.6
19	CAUTION SIGN STICKER <i>? free</i>	1 S	16.00 ✓	12.4
20	AIR CONDITIONER STICKER	1 S	9.00 ✓	6.64
SUB TOTAL SPARE PARTS		:	\$ 8,563.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	3	\$	797.00	+	
22	FRONT PARKING AID SEAL RING <i>new</i>	4	\$	10.00	+	
23	FRONT BUMPER WIRING SET new ✓ cut	1	\$	750.00	✓ 600	<i>sls.</i>
24	HORN HIGH TONE - LH <i>new</i>	1	\$	154.00	+	
25	HORN LOW TONE - RH	1	\$	146.00	+	
26	HORN BRACKET - LH / RH <i>new</i>	2	\$	50.00	+	
27	FRONT FENDER - LH / RH <i>new</i> <i>Buckled</i> ✓	2	\$	2,890.00	1156 con	<i>sls.</i>
28	FRONT FENDER BRACE - LH / RH <i>new</i>	2	\$	196.00	+	
29	FRONT FENDER BRACKET - LH / RH <i>new</i>	2	\$	78.00	+	
30	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$	520.00	+	
31	FRONT WHEEL HOUSING LINER COVER - LH / RH <i>new</i>	2	\$	36.00	+	
32	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$	44.00	+	
33	BONNET <i>Buckled</i>	1	\$	3,695.00	2956	
34	BONNET HINGE - LH / RH <i>new</i> ✓ <i>Best.</i>	2	\$	162.00	✓ 128.96 con	<i>sls.</i>
35	BONNET ATTACHMENT PARTS <i>new</i>	1	\$	309.00	+	
36	BONNET STRIKER - LH / RH <i>new</i>	2	\$	246.00	+	
37	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$	31.00	24.24	
38	BONNET LOCK - LH / RH <i>new</i>	2	\$	455.00	+	
39	BONNET SOUND ABSORBER <i>new</i>	1	\$	244.00	+	
40	BONNET RELEASE ELEMENT <i>new</i>	1	\$	65.00	+	
SUB TOTAL SPARE PARTS			\$	10,878.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
41	BONNET RELEASE LEVER <i>Not in</i>	1	\$	16.00	<i>+</i>	
42	BONNET BOWDEN CABLE - CENTER <i>Not in</i>	1	\$	64.00	<i>+</i>	
43	BONNET BOWDEN CABLE COVER	1	\$	11.00	<i>+</i>	
44	BONNET LOCK CABLE	1	\$	82.00	<i>+</i>	
45	BONNET LOCK CABLE COVER - LH / RH	2	\$	92.00	<i>+</i>	
46	PLENUM CHAMBER COVER <i>7 x Not in</i>	1	\$	144.00	<i>7 x con</i>	
47	HEADLIGHT MOUNTING - LH / RH <i>✓ cracked</i>	2	\$	264.00	<i>✓</i>	210.4 con
48	HEADLIGHT - LH / RH <i>LH cracked</i>	2	\$	11,904.00		59524761.6
49	HEADLIGHT HEAT SINK	1	\$	870.00	<i>+</i>	
50	HEADLIGHT POWER MODULE	1	\$	850.00	<i>+</i>	
51	HEADLIGHT HOSE - LH	1	\$	28.00	<i>+</i>	
52	LIFT CYLINDER - LH / RH <i>✓ Not in damaged</i>	2	\$	462.00	<i>✓</i>	184.4 con
53	LIFT CYLINDER HOSE	1	\$	92.00	<i>+</i>	
54	LIFT CYLINDER WASH WATER RESERVOIR <i>Not in</i>	1	\$	240.00	<i>+</i>	
55	LOCK CARRIER <i>cracked</i>	1	\$	1,412.00	<i>✓</i>	1129.6
56	A/C CONDENSER <i>Dented</i>	1	\$	605.00	<i>✓</i>	483.6
57	RADIATOR ADDITIONAL COOLER <i>Best</i>	1	\$	984.00	<i>✓</i>	786.8 con <i>sls</i>
58	RADIATOR <i>2 x Not in</i>	1	\$	1,093.00	<i>7 x con</i>	
59	READY-MIX COOLANT <i>in</i>	6	\$	297.00	<i>✓</i>	237.12
60	RADIATOR AIR GUIDE - LH / RH <i>Not in</i>	2	\$	86.00	<i>✓</i>	34.08 con <i>sls</i>
SUB TOTAL SPARE PARTS			\$	19,596.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 7901 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - UPPER / LOWER <i>Upper Canister</i>	2 S	96.00 <i>48</i>	37.84
62	AIR INTAKE COVER - UPPER <i>Ren</i>	1 S	64.00 <i>x</i>	
63	AIR INTAKE COVER - LOWER <i>? x } Ren</i>	1 S	59.00 <i>? x</i>	con
64	AIR INTAKE COVER - CENTER <i>? x }</i>	1 S	21.00 <i>x</i>	con
65	FRONT WHEEL COVER - LH / RH <i>Nec</i>	2 S	566.00 <i>✓</i>	452
66	FRONT NO PLATE <i>Perfed</i>	S/N S	60.00 <i>✓</i>	60
67	SUNDRIES <i>? ✓ Nec</i>	S	400.00 <i>✓</i>	74.72 con
TOTAL SPARE PARTS		:	\$	40,303.00
TOTAL LABOUR CHARGES		:	\$	15,172.00
GRAND TOTAL		:	\$	55,475.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian L
08/11/22

are Authorized, 08 Pys.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT