



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961
Registration No : SLK5322M
Chassis No : MRHGM6660HP000392
Model : CITY 1.5SV CVT 2017
Owner's Name : YEO KIONG MING SHAUN
Ins Policy No. :
Date of Accident : 4/11/2022

Document No. : SQT22003297
Date : 9. Nov 2022
Customer No. : WZA011
Svc Advisor : LEE CHEN SIN
Engine No : L15Z14113413
Date | Time : 9. Nov 2022 9:13:03 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: YEO KIONG MING SHAUN OWNER INSURER: INCOME INSURANCE LIMITED ACC DATE: 04/11/2022 SURVEYED BY: DATE: REF NO: TP INSURER: ALLIANZ INSURANCE SG TP VEH: YP4307J						
71101-T9A-T00ZZ	FACEFR.BUMPER <i>Repair</i>	1	459.80	25	344.85	24.14	368.99
91505-TM8-003	CLIP,BUMPER <i>X 11</i>	10	2.30	25	17.25	1.21	18.46
71198-T9A-T00	SPACERL.FR.BUMPER SIDE <i>7 X 11</i>	1	10.40	25	7.80	0.55	8.35
60260-T9A-T50ZZ	PANEL COMPL.FR.FENDER <i>34</i>	1	343.80	25	257.85	18.05	275.90
74150-T9A-T00	FENDER ASSYL.FR INNER <i>X 11</i>	1	76.80	25	57.60	4.03	61.63
91501-TR0-003	CLIP,INNER FENDER <i>m</i>	10	2.80	25	21.00	1.47	22.47
Sum Item					706.35	49.45	755.80
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00	250	280.00	19.60	299.60
BKFE11R	REMOVE & RENEW FR L FENDER & BUMPER <i>650 X 1.5</i>	1	1950.00	975	1950.00	136.50	2086.50
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) <i>@ 520 X 2</i>	1	1560.00	1040	1560.00	109.20	1669.20
Sum Labor					3890.00	272.30	4,162.30

Survey By RASU - Hy 90010068 4 days
Date & Time 12/12/22 @ 1200
Excess Ready before paint
Status _____
Total Amount 4,596.35 321.75 4,918.10
Total (Inclusive of GST) 4,918.10

Printed on 9/11/2022 9:21:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.