

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer: ALLIANZ INSURANCE SINGAPORE PTE

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

: YEO KIONG MING SHAUN

Registration No : SLK5322M

 Chassis No
 : MRHGM6660HP000392

 Model
 : CITY 1.5SV CVT 2017

Ins Policy No.

Owner's Name

Item

Date of Accident : 4/11/2022

Document No. : SQT:

: SQT22003297

Page

1

 Date
 : 9. Nov 2022

 Customer No.
 : WZA011

Svc Advisor : LEE CHEN SIN Engine No : L15Z14113413

Date | Time : 9. Nov 2022 9:13:03 AM

Surveyor Name :
Survey Date :
Authorisation Date :

7% GST Amount

Qty Unit Price Disc % Amount Amount incld GST

TP DIRECT SETTLEMENT (J/NO:

OWNER: YEO KIONG MING SHAUN

OWNER INSURER: INCOME INSURANCE LIMITED

ACC DATE: 04/11/2022

SURVEYED BY:

Description

DATE: REF NO:

TP INSURER: ALLIANZ INSURANCE SG

TP VEH: YP4307J

71101-T9A-T00ZZ	FACEFR.BUMPER	1	459.80	25	344.85	24.14	368.99
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
71198-T9A-T00	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
60260-T9A-T50ZZ	PANEL COMPL.FR.FENDER	1	343.80	25	257.85	18.05	275.90
74150-T9A-T00	FENDER ASSYL.FR.INNER	1	76.80	25	57.60	4.03	61.63
91501-TR0-003	CLIP,INNER FENDER	10	2.80	25	21.00	1.47	22.47
				Sum Item	<u>706.35</u>	<u>49.45</u>	<u>755.80</u>
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		280.00	19.60	299.60
BKFE11R	REMOVE & RENEW FR L FENDER & BUMPER	1	1950.00		1950.00	136.50	2086.50
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1560.00		1560.00	109.20	1669.20
				Sum Labor	<u>3890.00</u>	<u>272.30</u>	<u>4,162.30</u>
Survey By		,	,		,		_
Date & Time			To	otal Amount	4,596.35	321.75	4,918.10
Excess			Total (Inclus	sive of GST)			<u>4,918.10</u>
Status							

Printed on 9/11/2022 9:21:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer: ALLIANZ INSURANCE SINGAPORE PTE

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

: YEO KIONG MING SHAUN

Registration No : SLK5322M

 Chassis No
 : MRHGM6660HP000392

 Model
 : CITY 1.5SV CVT 2017

Ins Policy No.

Owner's Name

Date of Accident : 4/11/2022

Document No.

: SQT22003297

Page

2

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Date
Customer No.

: 9. Nov 2022 : WZA011

Svc Advisor

: LEE CHEN SIN

Engine No

: L15Z14113413

Date | Time

Qty

: 9. Nov 2022 9:13:03 AM

Surveyor Name
Survey Date

Authorisation Date

7% GST

Amount incld GST

Unit Price Disc % Amount Amount

Description

Signature

Item

Printed on 9/11/2022 9:21:11 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.