

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22011215/EWP3Q2**Date:** 07/06/2023**REFERENCE****Insured/Claimant:** KOH SEE KIAT **Policy No:** DMPCSNW00180492201**Date of Loss:** 05/11/2022 **Nature of Claim:** OD **Claim No:** SNM22D207996/C01/TAYHP**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SMD4193A
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) **Engine No:** G4FGJU186299
Reg. Date: 18/08/2018 (Man. Year: 2018) **Chassis No:** KMH841CMJU686455
Colour: Beige **Odometer:** 54450 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 **Rear Tyre Size:** 195/65 R15
Front Left Side: Tourador 4 mm **Rear Left Side:** Tourador 4 mm
Front Right Side: Tourador 4 mm **Rear Right Side:** Tourador 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,175.00	5,175.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	694.01	694.01	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,869.01	5,869.01	0.00	0.00
+ GST 7.00/8.00% (\$\$)	410.83	469.52	-58.69	-14.29
Nett Amount (\$\$)	6,279.84	6,338.53	-58.69	-0.93

INSPECTION

Date of Assignment: 09/11/2022 **Present Location:** Goldbell Engineering Pte Ltd (Tuas)
Date Inspected: 09/11/2022 **Inspected At:** PANDAN LOOP INDUSTRIAL ESTATE, #01-12
Estimated Period of Repair: 6.0 days **Repairer:** Goldbell Engineering Pte Ltd (Tuas)

Adjuster: CHEN TSUE YEE**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4193A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		4,855.00 F	*4,855.00 F
Supplementary #1						
2	1	HY86356-F2000MOBIS	*F RAD GRILL UPPER GARNISH	Broken	60.00 F	*60.00 F
3	1	KS1420608250B	*CLIP (6 PCS EACH \$2.50)	Necessary	15.00 F	*15.00 F
4	1	T08889-80110	*COOLANT (4L X4) RED CAP	Broken	26.00 F	*26.00 F
5	1	HY28210-F2000 MOBIS	*AIR DUCT B	Broken	65.00 F	*65.00 F
6	1	HY86513-F2000 MOBIS	*RETAINER F BUMPER LH	Broken	15.00 F	*15.00 F
7	1	HY64128-F2000	*HEADLAMP SUPT REINF RH	Broken	20.00 F	*20.00 F
8	1	HY82191-4H000	*BUMPER-DR OVERSLAM	Necessary	4.00 F	*4.00 F
9	1	HY86357-F2000	*F BUMPER UPPER STRIP	Broken	20.00 F	*20.00 F
10	1	HY86554-F2000	*F BUMPER BKT RH	Broken	20.00 F	*20.00 F
11	1	HY86553-F2000	*F BUMPER BKT LH	Broken	20.00 F	*20.00 F
12	1	HY64118-F2000	*HEADLAMP SUPT REINF LH	Broken	20.00 F	*20.00 F
13	1	HY29134-F2000	*GUARD-AIR-RH	Broken	35.00 F	*35.00 F
Total Parts (S\$)						5,175.00
						5,175.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Labour	New	694.01	694.01
Gross Labour Cost (\$\$)			694.01	694.01

Report was unsubmitted during this print-out.

< END OF ESTIMATES >