

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 22 Dec 2022

Preliminary Advice

Vehicle No	: SMD4193A	Accident Date	: 05/11/2022
Make	: HYUNDAI ELANTRA	Policy No.	: DMPCSNW00180492201
Assignment Date	: 09/11/2022	Excess	: S\$0.00
Date of Inspection	: 09/11/2022	Est. Duration of Repair	: 06 DAYS
Inspection At	: GOLDBELL ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,798.01 (Est \$5,549.01 + Supp \$ 294.00)
Revised Amount	:S\$	5,843.01
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,843.01

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	28,370.00
Margin for Repair	:S\$	43,630.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair. Please approve on Supplementary.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.