

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 09 Nov 2022

## **Preliminary Advice**

Vehicle No	: SMD4193A	Accident Date	: 05/11/2022
Make	: HYUNDAI ELANTRA	Policy No.	: DMPCSNW00180492201
Assignment Date	: 09/11/2022	Excess	: S\$0.00
Date of Inspection	: 09/11/2022	Est. Duration of Repair	: 06 DAYS
Inspection At	: GOLDBELL ENGINEERING PTE LTD		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,549.01
Revised Amount	:S\$	4,844.01
Check Items (Estimated)	:S\$	640.00
Total	:S\$	5,484.01

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	28,370.00
Margin for Repair	:S\$	43,630.00

### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.