

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SHC8462L
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 03.10.2022
 Insurance: INCOME
 MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	RADIATOR GRILLE			\$ 1,409.10	✓
1	FRT BUMPER			\$ 481.10	Rp
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50	✓
10	FRT BUMPER CLIPS			\$ 22.00	✓
1	FRT BUMPER CENTRE GRILLE			\$ 318.80	X nn.
	SUB TOTAL		1799.60	\$ 2,599.50	
	LESS 20%		1439.68	\$ 519.90	
	DISCOUNTED TOTAL			\$ 2,079.60	
	Labour Charge				
	PANEL BEATING			\$ 400.00	350
	SPRAY PAINTING CHARGE		600	\$ 300.00	250
	CHECK ALL LIGHTING			\$ 60.00	X nn.
	TOTAL LABOUR			\$ 700.00	
	Emblem-Blue Drive (LH/RH)		\$2039.68		
	ESTIMATE TOTAL		2 days	\$ 2,779.60	*

Nett
nett

350
250
X nn.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97495749
 wp 3/10/22 e 345
 02 days
 P/p Resurvey new parts
 tanji e lkh auto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: