

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC8747R

Make : HYUNDAI

Model : I-40

Date: 03/10/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			\$ 1,052.20	h
10	FRT BUMPER CLIPS			\$ 22.00	na
1	FRT BUMPER SIDE BRACKET RH			\$ 28.60	de
1	HEADLAMP RH			\$ 1,388.00	X } n n X
1	FRT BUMPER GRILLE RH			\$ 187.20	X } n n X
1	RADIATOR GRILLE			\$ 1,480.00	one
1	RADIATOR GRILLE H EMBLEM			\$ 129.50	ne
1	FRT BUMPER REINFORCEMENT			\$ 588.40	X } n n X
1	HEADLAMP SUPPORT PANEL			\$ 907.40	X } n n X
			2712.30		
			2169.84		
	SUB TOTAL			\$ 5,783.30	
	LESS 20%			\$ 1,156.66	
	DISCOUNTED TOTAL			\$ 4,626.64	
					Nett
				\$ -	Nett
	Labour Charge				
	PANEL BEATING			\$ 600.00	280
	SPRAY PAINTING CHARGE - LH RH A PILLAR		530	\$ 300.00	250
	TUFF KOTE			\$ 60.00	X n n
	CHECK ALL LIGHTING			\$ 60.00	X n n
	TOTAL LABOUR		2699.84	\$ 1,020.00	
			4582150		
	ESTIMATE TOTAL		02 days	\$ 5,646.64	
			*		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9741574 1
 WP 2/10/22 @ 4pm
 02 days
 L/S Resurvey after repair
 Tanpin @ Whantow

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer

Signature: