

100

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7222P

Make : HYUNDAI

Model : IONIQ(G2)

Date: 10/01/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 459.40
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR FENDER RH			\$ 1,768.30
1	REAR BUMPER SIDE BRACKET RH			\$ 55.80
1	RR WHEEL HUB CAP RH			\$ 346.40
1	FRT DOOR MIRROR ASSY RH			\$ 1,391.70
1	REAR FENDER SHIELD RH			\$ 173.60
1	DELTA GARNISH RH			\$ 42.80
1	FRT PILLAR UPPER COVER			\$ 89.60
	SUB TOTAL			\$ 4,349.60
	LESS 20%			\$ 869.92
	DISCOUNTED TOTAL			\$ 3,479.68
	REAR TYRE RH			\$ 70% 216.00
	REAR FENDER ADVERTISEMENT STICKER RH			\$ 100.00
			NETT	\$ 316.00
	Labour Charge			
	PANEL BEATING			\$ 1,050.00
	SPRAY PAINTING CHARGE			\$ 1,000.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	CHECK LIGHTING			\$ 60.00
	TUFF KOTE			\$ 60.00
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR			\$ 120.00
	TOTAL LABOUR			\$ 2,350.00
	ESTIMATE TOTAL			\$ 6,145.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 up 3/10/22 @ 430pm
 4/9 Repair after repair
 Tanpin e khando.com
 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 01.10.2022 10:54

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4937190

JC No: 805531872

CUSTOMER
NAME: COMFORT TRANSPORTATION PTE LTD
V/MS: 7010045
CUSTOMER NO: 383 SIN MING DRIVE
ADDRESS: Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)


SCOUNT CARD NO.

REGN NO. SHD7222P	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 30.09.2022 20:10
YR OF MANU. 22.11.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU114449	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 30.09.2022
NATURE: 3P 30.09.2022

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD7222P YY

Vehicle No.: SHD7222P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard