

MFORT TRANSPORTATION PTE LTD

PAIR ESTIMATE

Vehicle No. : SHD7222P

Date: 10/01/22

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 459.40
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR FENDER RH			\$ 1,768.30
1	REAR BUMPER SIDE BRACKET RH			\$ 55.80
1	RR WHEEL HUB CAP RH			\$ 346.40
1	FRT DOOR MIRROR ASSY RH			\$ 1,391.70
1	REAR FENDER SHIELD RH			\$ 173.60
1	DELTA GARNISH RH			\$ 42.80
1	FRT PILLAR UPPER COVER			\$ 89.60
	Arm assy - 265.40 bt			
	wheel assy - 1124.20 bt			
	SUB TOTAL		3609.10	\$ 4,349.60
	LESS 20%		2887.28	\$ 869.92
	DISCOUNTED TOTAL			\$ 3,479.68
	REAR TYRE RH		151.20	\$ 70% 216.00
	REAR FENDER ADVERTISEMENT STICKER RH		100	\$ 100.00
			251.20 NETT	\$ 316.00
	Labour Charge			
	PANEL BEATING			\$ 1,050.00
	SPRAY PAINTING CHARGE			\$ 1,000.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	CHECK LIGHTING			\$ 60.00
	TUFF KOTE			\$ 60.00
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR			\$ 120.00
	TOTAL LABOUR		4293.48	\$ 2,350.00
	ESTIMATE TOTAL		4583450	\$ 6,145.68
			03 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 up 3/10/22 @ 430pm
 4/5 Resurvey after repair
 Tanpin e lkhants.u.n
 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
ARM ASSY-RR TRAILING ARM RH	1		\$265.40	b7 ✓
WHEEL ASSY-ALUMINIUM (BLACK)	1		\$1,124.20	b7 ✓
TOTAL			\$1,389.60	