

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22011229/Swp3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 24/11/2022 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 8825T FBU 3674B Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S2M04EAT Excess (\$) 0.00 ANG YVONNE **Assign Date** 09/11/2022 Assign From **Vehicle Particulars & Condition** 2. HONDA REVO X Make & Model 110 c.c HIDDEN 2022 Engine No. Year of Reg. MH1JBK316NK430071 BLACK / RED Chassis No. Colour Odometer 9300 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/90-17 **FEDERAL** 5 mm L/H Front Tyre mm 80/90-17 FEDERAL R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, O/S & N/S BODY. 5. **General Information** 05/11/2022 09/11/2022 (04:20 PM) Inspect Date / Time Accident Date **EQBH PTE LTD** Survey held at 25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500

Report Ref No. CS3/ASM22011229/Swp3m4

Estimate Days of Repair

Inspected By

5b.

S MOHAMED IRFAN BIN MOHAMED IQUBAL

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

3 Working Days