



28 November 2022

REG NO. : SMM 9886 D  
MAKE/MODEL : SUBARU FORESTER

### ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY                               | DESCRIPTION                                              | AMT(\$)    |
|-----------------------------------|----------------------------------------------------------|------------|
| <b>netf <del>LIST</del> ITEMS</b> |                                                          |            |
| 1                                 | Front bonnet                                             | 982.00 X   |
| 1                                 | Front bonnet chrome moulding                             | 180.40 X   |
| 1                                 | Front bonnet lock                                        | 115.00 X   |
| 2                                 | Front headlamps                                          | 5,420.00 X |
| 1                                 | Front grille assy                                        | 360.00 X   |
| 1                                 | Front grille logo                                        | 75.00 X    |
| 1                                 | Front grille lower chrome moulding                       | 396.80 X   |
| 1                                 | Front bumper                                             | 794.60     |
| 2                                 | Front bumper fog lamps                                   | 720.80 X   |
| 2                                 | Front bumper fog lamp chrome mouldings                   | 156.00 X   |
| 1                                 | Front bumper reinforcement                               | 395.00     |
| 2                                 | Front bumper side retainers                              | 139.00 X   |
| 1                                 | Front bumper tow hook cover                              | 16.00      |
| 1                                 | Rear windscreen moulding                                 | 84.05      |
| 1                                 | Rear tailgate                                            | 1,400.61   |
| 1                                 | Rear tailgate lock                                       | 176.40     |
| 1                                 | Rear tailgate logo                                       | 88.00 X    |
| 1                                 | Rear tailgate rubber                                     | 121.80     |
| 1                                 | Rear tailgate "AWD" emblem                               | 72.05      |
| 1                                 | Rear tailgate "FORESTER" emblem                          | 72.05      |
| 1                                 | Rear tailgate "SUBARU" emblem                            | 42.90      |
| 2                                 | Rear taillamps                                           | 874.10 X   |
| 1                                 | Rear end panel                                           | 320.10     |
| 1                                 | Rear end panel inner garnish                             | 40.00      |
| 1                                 | Rear keyless sensor                                      | 195.85 X   |
| 1                                 | Rear bumper                                              | 700.00     |
| 1                                 | Rear bumper beam                                         | 195.00 X   |
| 1                                 | Rear bumper inner sponge                                 | 121.60 X   |
| 2                                 | Rear bumper reflectors                                   | 91.40 X    |
| 1                                 | Rear bumper reinforcement                                | 320.00     |
| 2                                 | Rear bumper side retainers                               | 97.20      |
| 1                                 | Rear spare tyre <del>board</del> tools <del>sponge</del> | 320.55     |
| 1                                 | Rear exhaust silencer                                    | 601.20 X   |
| 2                                 | Rear exhaust mountings                                   | 57.00 X    |
| 1                                 | Rear exhaust chrome pipe                                 | 105.50 X   |
|                                   |                                                          | 15,847.96  |
|                                   | Less 10%                                                 | 1,584.80   |
|                                   |                                                          | 14,263.16  |



**SPECIAL NETT ITEMS**

|   |                                |        |    |        |        |
|---|--------------------------------|--------|----|--------|--------|
| 1 | Front bumper clip (1 set)      | nee    | \$ | 60.00  | 50     |
| 1 | Front number plate with holder | sent   | \$ | 50.00  | 40     |
| 1 | Rear windscreen sealant        | nee    | \$ | 80.00  | 40     |
| 1 | Rear reverse sensor (1 set)    | should | \$ | 350.00 | 200    |
| 1 | Rear bumper clip (1 set)       | nee    | \$ | 60.00  | 50     |
|   |                                |        |    | <hr/>  |        |
|   |                                |        |    | \$     | 600.00 |

**S/N**

**LABOUR CHARGES**

|    |                                                              |    |    |          |          |
|----|--------------------------------------------------------------|----|----|----------|----------|
| 1  | To check wiring and reset headlamps focusing.                |    | \$ | 80.00    |          |
| 2  | To remove, replaced damaged lamps and check up rear wiring.  |    | \$ | 80.00    | 330      |
| 3  | To remove and refit inner garnishes.                         |    | \$ | 150.00   | 80       |
| 4  | To remove and refit rear reverse sensor.                     |    | \$ | 150.00   | 50       |
| 5  | To transfer rear tailgate mechanism and wiring assembly.     |    | \$ | 80.00    | 60       |
| 6  | To remove and refit rear windscreen glass.                   |    | \$ | 180.00   | 120      |
| 7  | To remove, refit and replace exhaust silencer and mountings. | 11 | \$ | 150.00   | X        |
| 8  | To apply undercoating.                                       |    | \$ | 200.00   | 60       |
| 9  | Panel beating.                                               |    | \$ | 1,600.00 | 1100     |
| 10 | To re-spray painting on the affected areas.                  |    | \$ | 1,500.00 |          |
|    |                                                              |    |    | <hr/>    |          |
|    |                                                              |    |    | \$       | 4,170.00 |

**GRAND TOTAL :**

**\$ 19,033.16**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

4725-71  
102  
4253-13  
380  
2900  
7533-1