

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
19 UBI ROAD 4  
SINGAPORE 408623  
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0430/22

DATE : 04-NOV-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
S(079909)  
TEL : 63896111  
FAX : 62247175

OWNER'S NAME : M/S CASUARINA CURRY BANANA LEAF PTE LTD  
ADDRESS : 187 MACPHERSON RD  
SENNETT ESTATE  
S(348545)  
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : 22-MW002343-R07  
VEHICLE NO : GBC9546T  
MODEL CODE : MVL2RDKE26KW3GBR-D  
MODEL/YEAR : NISSAN NV350 PANEL VAN AT EURO5  
ENGINE NO : YD25342269A  
CHASSIS NO : JN1MC2E26Z0001629  
MILEAGE : 162789 KM  
DATE IN : 04/11/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : ELMER  
ACCIDENT DATE : 29/10/2022

-9645 0057 elmer @ fanchong - Cnn

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBC9546T

-----

| S/NO | JOB CODE | NATURE OF JOB                                                                                             | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATION |
|------|----------|-----------------------------------------------------------------------------------------------------------|----------------------|------------------------------|
| 1    | ZZ/001   | CHARGES TO REPAIR BOTH RR FENDER & INNER RR FENDER<br>RENEW OUTER RR END PANEL, TAIL GATE AND REAR BUMPER | 1400.00              |                              |
| 2    | ZZ/002   | CHARGES TO SPRAY PAINTING SAME                                                                            | 1250.00              |                              |
| 3    | ZZ/003   | RENEW REAR WINDSCREEN GLASS                                                                               | 240.00               |                              |
| 4    | ZZ/004   | APPLY SEALANT TO TAIL GATE AND OUTER RR END PANEL                                                         | 200.00               |                              |
| 5    | ZZ/005   | REMOVE AND TRANSFER TAIL GATE MECHANISM                                                                   | 120.00               |                              |
| 6    | ZZ/006   | TO REMOVE AND INSTALL BOTH RR COMB LAMP<br>AND CHECK REAR WIRING SYSTEM                                   | 80.00                |                              |
| 7    | ZZ/007   | RENEW REVERSE SENSOR                                                                                      | 110.00               |                              |
|      |          | TOTAL LABOUR CHARGES                                                                                      | 3400.00              |                              |

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBC9546T

-----

| S/NO                                                  | PARTS DESCRIPTION               | PARTS NUMBER | DAMAGED PARTS & PRICES |      |              |
|-------------------------------------------------------|---------------------------------|--------------|------------------------|------|--------------|
|                                                       |                                 |              | NETT                   | LIST | S/NETT REMAR |
| 1                                                     | REAR W/SCREEN SEALANT           | SEALANT - 4  |                        |      | 80.00        |
| 2                                                     | SUNDRIES                        | NPN          |                        |      | 50.00        |
| 3                                                     | SENSOR-REVERSE                  | SENSOR       |                        |      | 250.00       |
| 4                                                     | EMBLEM-BACK DOOR NV350 URVAN    | 90890-3XY0A  | 118.70                 |      |              |
| 5                                                     | 70KM/H                          | 70KM/H       |                        |      | 15.00        |
| 6                                                     | EMBLEM-REAR NISSAN              | 90890-JX00A  | 70.00                  |      |              |
| 7                                                     | RR END CARPET PLATE             | 74990-3XA0A  | 64.70                  |      |              |
| 8                                                     | OUTER RR END PANEL              | 75615-3XA0A  |                        |      | 158.80       |
| 9                                                     | WEATHER STRIP TAIL GATE         | 90830-3XA0A  | 145.00                 |      |              |
| 10                                                    | GLASS-TAIL GATE                 | 90300-3XA0A  | 961.20                 |      |              |
| 11                                                    | TAIL GATE                       | K010M-3XBAA  | 2157.10                |      |              |
| 12                                                    | INNER BRACKET RR BUMPER         | 85040-VZ00A  | 185.80                 |      |              |
| 13                                                    | CLIP RR BUMPER @ SGD\$1.40 EACH | 01553-05323  | 14.00                  |      |              |
| 14                                                    | REAR BUMPER                     | 85022-3XA0A  | 720.60                 |      |              |
| SUB TOTAL                                             |                                 |              | 4437.10                | 0.00 | 553.80       |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                                 |              | 887.42                 | 0.00 | 0.00         |
| GRAND TOTAL                                           |                                 |              | 3549.68                | 0.00 | 553.80       |
| OVERALL TOTAL                                         |                                 |              | 4103.48                |      |              |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

## SUMMARY OF ESTIMATE FOR VEHICLE REGN NO GBC9546T

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 3400.00   |
| TOTAL SPARE PARTS CHARGES | 4103.48   |
|                           | -----     |
| GRAND TOTAL               | 7503.48 * |
|                           | -----     |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.