



樹發汽車修理廠

SHU FATT AUTO WORKS

send offer

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
4th November 2022
China Taiping- TP

Steve (LKK)

9/11/22, 4.30 pm

m n

L/S, My AC sy, 5 dys

SKE 3281 D BMW Z4

Spare Parts	Description	Price	Nett
1	✓ Rt door. / 00	2176.60	Nett
1	✓ Rt door glass. - BR	482.95	Nett
1	✓ Rt door glass regulator. ? - bent ✓	489.05	Nett
1	Rt door glass regulator motor. ? x nn	328.55	Nett
1	✓ Rt door glass outer moulding. - CRV	142.25	Nett
1	✓ Rt door glass inner moulding. - CRV	289.15	Nett
1	Rt door outer handle. ? x nn	898.55	Nett
1	✓ Rt wing mirror. - BR	871.75	Nett
1	✓ Rt wing mirror cover. - mis	185.05	Nett
1	✓ Rt wing mirror glass. - BR	241.45	Nett
1	✓ Rt door rubber. - n/c	95.50	Nett
2	Rt door hinges. @\$78.05 ? x nn	156.10	Nett
1	✓ Rt door inner board. ? - deformed ✓	2572.50	Nett
1	✓ Rt frt windscreen pillar moulding. - cut	425.10	Nett
1	Rt wing mirror inner cover. ? x nn	121.55	Nett
1	Rt wing mirror inner cover speaker. ? x nn	86.10	Nett
1	Rt body rubber. X nn	155.50	Nett
1	Set rear bumper clips. X nn	60.00	Nett
2	Rear bumper side retainers. @\$190.80 X nn	381.60	Nett
1	Rt frt fender emblem. - n/c	110.95	Nett
1	Rt frt fender 'S Drive 2.0i' emblem. - n/c	155.35	Nett
1	Rt rear rim. X nn	1337.50	Nett

Labour	Description	Price	Nett
	To knock, straighten rt frt fender, rt rear fender, rt door frt pillar, rt door rear pillar, renew rt door and assembly.	11773.10	
	To respray damaged parts.	1050.00	400
	To remove, replace rt door glass, regulator, motor, board, inner lock, outer lock, mouldings, rubbers and assembly.	1050.00	1,000
	To remove carpets, upholstery, seats to facilitate repairs and assembly.	250.00	100
	To reseal joints, reinsulate, anti rust panels and assembly.	120.00	50
	To remove, replace rt rear rim, tyre and assembly.	60.00	30
	To check and adjust wheel alignment.	80.00	X nn
	To check an reset ECU.	150.00	X nn
		150.00	✓

14683.10

Cinturato 225/45R17
WBALL32020J080122
64519

Supplth

- ① Right rocker gearish. de ✓
- ② Right door gearish. dis ✓

Parts: 8758.60 (incl. Supp)
-5%: (427.93)
8320.67
labour: 1730.00
10,050.67
-20%: (2010.13)
8040.53
45: 8050.00



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
4th November 2022

Supplementary
China Taiping- TP

SKE 3281 D BMW Z4

Spare Parts	1	Right rocker garnish.	S\$	
			385.30	<i>de ✓</i>
	1	Right door frame garnish.	135.65	<i>dis ✓</i>

			520.95	
			Less 5%	(26.05)

			494.90	