



WING YIP

永業摩托

Date : 08-Nov-22

ASSESSMENT FOR REPAIR

REG.NO : FBJ 604 G (Honda MSX 125)
 Name : Mr Chong Koang Yih

01	FRONT FENDER (BROKEN) <i>cut</i>	1 pc.,	168.00	✓
02	THROTTLE CABLE (SCRATCHED) <i>cut</i>	1 set.,	58.00	X
03	HANDLE BAR (BEND) <i>1/2</i>	1 pc.,	68.00	✓
04	HANDLE BAR HOLDER (BEND) <i>gr</i>	1 set.,	78.00	✓
05	HANDLE GRIP (SCRATCHED) <i>Hee</i>	1 set.,	16.00	✓
06	BAR END PUSH (SCRATCHED) <i>cut</i>	1 set.,	30.00	✓
07	LEVER SET (SCRATCHED) <i>cut</i>	1 set.,	56.00	✓
08	HEADLAMP COVER (L) (SCRATCHED) <i>cut</i>	1 pc.,	118.00	✓
09	MIRROR SET (SCARTCHED) <i>cut</i>	1 set.,	78.00	✓
10	VISOR (BROKEN & SCRATCHED) <i>cut</i>	1 pc.,	85.00	✓
11	TANK COVER (RIGHT) (SCRATCHED) <i>cut</i>	1 pc.,	118.00	✓
12	NUMBER PLATE HOLDER (BEND) <i>1/2</i>	1 pc.,	158.00	✓
13	REAR WHEEL SHAFT (BEND) <i>cut</i>	1 pc.,	28.00	X
14	REAR WHEEL BEARING (DAMAGED) <i>cut</i>	2 pc.,	56.00	X
15	SPROCKET HUB BEARING (DAMAGED) <i>cut</i>	1 pc.,	28.00	X
16	EXHUAIST END CAN (SCRATCHED & BEND) <i>cut</i>	1 pc.,	418.00	✓
17	EXHUAIST COVER (SCRATCHED) <i>cut</i>	1 pc.,	88.00	✓
18	PILLION FOOTPEG (R) (SCRATCHED) <i>cut</i>	1 pc.,	28.00	✓
19	FRONT SIGNAL (R) (BROKEN) <i>broken</i>	1 pc.,	80.00	✓
20	REAR SIGNAL (L) (BROKEN) <i>cut</i>	1 pc.,	80.00	✓
21	REAR TYRE (DAMAGED) <i>cut</i>	1 pc.,	98.00	X
22	REAR RACK (BEND) <i>defunct</i>	1 pc.,	128.00	✓

Sub/Total \$ 2,063.00

23	STEERING CONE BEARING (DAMAGED)	X 1	100.00	80/-
24	NUMBER PLATE (DAMAGED) <i>cut</i>	1 set.,	58.00	30/-
25	SPRAY PAINT	X 1	150.00	✓
26	WORKMANSHIP	1 Set.,	400.00	350/-
27	TOWING SERVICE	X 1	60.00	30/-

Sub/Total \$ 2,831.00

ADD GST 7% \$ 198.17

Grand Total \$ 3,029.17

6 days 2/5/22

2255.50
2/5 1800/-