



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011236/Rwy3m4	
			Date: 22/12/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4504B	Veh. Inspected	FBJ 604G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/10/22/2099	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	09/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MSX125	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	MLHJC61A9D5003846	Colour	WHITE	
Odometer	34723 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70-12	TIMSUN	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70-12	TIMSUN	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2022	Inspection Date	09/11/2022	
Survey held at	WING YAP MOTOR BLK 4003 #01-114 AMK AVE 10 IND PARK 1 SINGAPORE 569624			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	