



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Allianz Insurance Singapore Pte. Ltd.
ATTN : Motor Claim Department
TEL. NO. : 6714 3369
EMAIL : claims@allianz.com.sg

CC : Hong Aik Engineering Pte Ltd

DATE : 08.11.2022

VEHICLE NO. : XE 6942 G
MODEL NO. : MIT FUSO FV70HJD2VDEA
CHASSIS NO. : FV70HJA00194
ENGINE NO. : 470912C0502544 (10677 cc)
LTA REG DATE : 24.12.2021 - 23.12.2031

CLAIM TYPE : Third Party - XD 9601 B
D.O.A : 04.10.2022
CLAIM REF NO. : asm/AC22113/JL

QUOTATION FOR ACCIDENT REPAIR

<u>S/N</u>	<u>SPARE PARTS</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Corner panel, LH	1	pc	\$ 564.77	\$ 564.77
2	Door panel, LH	1	unit	\$ 3,182.28	\$ 3,182.28
3	Mark, Bluetec	1	pc	\$ 46.06	\$ 46.06
4	Decal, Shift pilot	1	pc	\$ 11.42	\$ 11.42
5	Door signal lamp, LH	1	pc	\$ 123.36	\$ 123.36
SUB-TOTAL :					\$ 3,927.89
LESS 25% :					\$ 981.97
TOTAL PARTS :					\$ 2,945.92

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	To remove and replace door panel, transfer door mechanism into new door panel, realign LHS door. Including replace other damaged parts.	\$ 1,750.00
2	Spray painting	\$ 600.00
TOTAL LABOUR :		\$ 2,350.00
GRAND TOTAL :		\$ 5,295.92