



(A) XE6942G

(B) XD9601B with
TRD8443T

Describe Circumstances of the Accident

On 4/10/22 around 15:00 hours, I was driving company vehicle XE6942G inside 131 Lorong Semang Ea. There was vehicle XD9601B stopped in front and his right side got space. Thus, I moved forward my vehicle. However, when I reached the place, there was no enough space for me to pass through. I then stopped my vehicle and waiting inside my vehicle. Suddenly, the vehicle XD9601B reversing, I quickly sounded horn to him, his trailer rear right corner hit onto my vehicle left front side.