

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 04 Jul 2023

**Preliminary Advice**

Insured Vehicle No	: YQ2251T		
TP Vehicle No	: SHD6651R	Accident Date	: 07/11/2022
Make	: MERCEDES-BENZ E220 BLUETEC	Assignment Date	: 10/11/2022
Date of Inspection	: 09/11/2022	Est. Duration of Repair	: 10
Inspection At	: BIFROST AUTO PTE LTD (KAKI BUKIT) 8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT SINGAPORE 415875		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,103.89
Revised Amount	:S\$	22,085.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	22,085.65
Lump Sum Repair	:S\$	15,000.00

**Total Loss Consideration**

New for Old Value	:S\$	
Book Value (Est)	:S\$	52,964.28
COE / PARF Rebate	:S\$	36,492.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,472.28

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair
  
- ( x ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.