



## Final Report

Estimate No. : **b1 63948**  
Date Estimated : **08/11/2022**  
Prepared By : **Han Kwan Yong**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Lin Rui**  
**35 Miltonia Street**  
**#06-30 Skies**

**Singapore 768065**

**- ACCOUNT - 49635**

**SMRT Buses Ltd**  
**60 Woodlands Industrial Park E4**

**Singapore 757705**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLQ8989M	WBATY920109F49872	31/05/2021	X3 M40i	20936

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include making good the rear RH fender, rear RH wheel arch cover and knocking out dents caused by the accident	1,700.00	0.00	1,700.00
To respray rear bumper, rear RH fender and rear RH wheel arch cover	2,533.00	0.00	2,533.00
To remove and install boot compartment carpet and garnish to facilitate repair	257.00	0.00	257.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RH BUMPER GUIDE	163.55	1.00	0.00	163.55
REAR BUMPER PANEL PRIMED (M/PMA)	1,536.45	1.00	0.00	1,536.45
EXPANDING RIVET BLACK	1.40	10.00	0.00	14.00

**# SUPPLEMENTARY ITEMS**

Total Labour :	4,906.00
Total Parts :	1,714.00
Total Labour & Parts :	6,620.00

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

