

ASS. REC. BY:

REF:

ALS/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Munich

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


2/c

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

889K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMQ 8827K Yr Regn: 12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel Astra

C.C.

1598

Colour

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W0VBD8EG5K 8034981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/R/m / STD A/R/m or

Tyre Size:

Continental 205/55R16

R: Triangle

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

9

mm

L/Bal.

8

mm

L/Bal.

9

mm

D.O.A.

05/11/22

D.O.I.

15/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fr & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1. Cut off Motion Plat

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ - RS - \$

Fees:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	05/11/2022
Vehicle Reg. No.:	SMQ8827K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL ASTRA ST, 1.6 D TURBO DIESEL (A)	Vehicle Reg. Date:	09/12/2019
Vehicle Colour:	RED	Chassis No:	W0VBD8EG5K8034981
Engine No:	A2183359JR5X0219		
Odometer:	114780 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 12 ✓

*NOT within
Policy Bk limit
Ex \$2000*

Present Location: **MUNICH AUTOCARE PTE LTD (HQ)****COST OF CLAIMS**

	Amount
Parts	24,019.60
Miscellaneous Items	269.00
Labour	5,530.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	29,818.60
- Excess (S\$)	2,000.00
(S\$)	27,818.60
+ GST 7.00% (S\$)	1,947.30
Nett Amount (S\$)	29,765.90

This claim is handled by: **LIM JIA HAW**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2022)

Parts: 144 OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	39054067	*FRONT BONNET	R1 0.00	0.00	*1,023.00 F	✓
2	1	39032149	*FRONT BONNET HINGLE LH	D11 0.00	0.00	*32.00 F	✓
3	1	39032150	*FRONT BONNET HINGLE RH	0.00	0.00	*32.00 F	7
4	1	39041995	*FRONT DOOR WING MIRROR	0.00	0.00	*98.40 F	7
5	1	39111554	*FRONT SIDE MIRROR LH	M3C/M 0.00	0.00	*303.00 F	✓
6	1	39081894	*FRONT HEADLAMP LH	M3C/M 0.00	0.00	*665.60 F	✓
7	1	13426393	*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	*65.00 F	7
8	1	39011390	*FRONT FENDER LH	R1 0.00	0.00	*442.00 F	✓
9	1	39115547	*FRONT FENDER INNER SHIELD LH	T1 0.00	0.00	*76.80 F	✓
10	1	13491088	*FRONT FENDER LAMP LH	M3 D11 0.00	0.00	*45.00 F	✓
11	1	39086891	*FRONT FENDER BRACKET	R1 0.00	0.00	*22.40 F	✓
12	1	39052728	*FRONT BUMPER	Bvc/UM 0.00	0.00	*1,632.80 F	✓
13	1	39086895	*FRONT BUMPER RETAINER LH	D11 0.00	0.00	*31.20 F	✓
14	1	13481997	*FRONT BUMPER FOG LAMP COVER	M11 0.00	0.00	*180.70 F	✓
15	1	39098907	*FRONT BUMPER FOG LAMP LH	0.00	0.00	*295.10 F	7
16	1	39160867	*FRONT DOOR LH	R1 0.00	0.00	*1,508.00 F	✓
17	1		*FRONT DOOR HINGLE UPP	R1 0.00	0.00	*146.00 F	✓
18	1		*FRONT DOOR HINGLE LOW	R1 0.00	0.00	*146.00 F	✓
19	1	39117456	*FRONT ROCKER PANEL MOLDING	K 0.00	0.00	*1,327.00 F	X
20	1	39024544	*FRONT RIM LH	CMT 0.00	0.00	*276.00 F	✓
21	1	YQ00956280	*FRONT PRESURE SWITCH LH	0.00	0.00	*164.00 F	7
22	1	39163258	*ROOF CURTAIN AIRBAG LH	Burn 0.00	0.00	*2,346.00 F	✓
23	1	39023001	*FRONT SEAT AIR BAG	✓ 0.00	0.00	*2,346.00 F	✓
24	1	39201592	*FRONT SEAT BELT LH	Tm 0.00	0.00	*792.00 F	✓
25	1	39201593	*FRONT SEAT BELT RH	Tm 0.00	0.00	*792.00 F	✓
26	1	39201587	*REAR SEAT BELT LH	Tm 0.00	0.00	*601.00 F	✓
27	1	39201587	*REAR SEAT BELT RH	Tm 0.00	0.00	*601.00 F	✓
28	1	39040242	*TRIM , REAR PILLAR LOWER RH	✓ 0.00	0.00	*53.00 F	X
29	1	39040243	*TRIM , REAR PILLAR LOWER LH	0.00	0.00	*53.00 F	7
30	1	39052732	*TRIM , REAR QUARTER UPPER RH	✓ 0.00	0.00	*79.00 F	X
31	1	39052731	*TRIM , REAR QUARTER UPPER LH	0.00	0.00	*79.00 F	7
32	1	39030299	*FRONT WHELL KNUCKLE ARM LH	R1 0.00	0.00	*520.00 F	✓
33	1	13517459	*FRONT WHELL HUB	R1 0.00	0.00	*579.00 F	✓
34	1	39089344	*FRONT WHELL LOWER ARM LH	B1 0.00	0.00	*619.00 F	✓
35	1	39039573	*FRONT SHOCK ABSORBER LH	R1 0.00	0.00	*314.00 F	✓
36	1	42705813	*FRONT STABILIZER BAR LINK	0.00	0.00	*97.00 F	7
37	1		*FRONT TIE ROD LH	0.00	0.00	*110.00 F	7
38	1		*FRONT TIE ROD RACK END LH	0.00	0.00	*135.00 F	7
39	1	95522359	*FRONT DRIVER SHAFT	0.00	0.00	*1,236.00 F	7
40	1	95529431	*FRONT STEERING RACK	R1 0.00	0.00	*1,972.00 F	7

F=Franchise part.

Sub Total (\$\$)	21,836.00
+ Margin on L,N Items 10.00% (\$\$)	2,183.60
Total Parts (\$\$)	24,019.60

Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	7	BUMPER CLIP	49.00
2	10	FENDER INNER SHIELD CLIP LH	70.00
3	1	FRONT TYRE LH	115.00
4	1	QUOTER GLASS SEALANT	35.00
Sub Total (S\$)			269.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET, BUMPER, FENDER LH, PILLAR LH, FRONT DOOR LH, SIDE MIRROR LH, ROCKER PANEL LH SIDE AND DAMAGE AREA	New	1,800.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
4	TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00
5	TO CONDUCT 4 WHEEL ALIGNMENT AND BALANCING	New	120.00
6	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH AND FRONT SEAT CUSHION AIR BAG LH	New	380.00
7	TO REMOVE & INSTALL FRONT LH AND REAR LH SUSPENSION AND UNDERCARRIAGE CONTROL SYSTEM AND INCLUDING TO REPLACE DAMAGED PART	New	380.00
8	TO DISMANTLE ROOF LINING AND INSTALL ALL ELECTRICAL COMPARTMENTS, CONTROL UNITS AND SIDE COMPARTMENT TRIM BOARD TO REPLACE LEFT SIDE CUSHION AIR BAG	New	350.00
9	TO REMOVE & REFIX QUOTER GLASS	New	80.00
10	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER, BONNET, BUMPER, FENDER LH, PILLAR LH, FRONT DOOR LH, SIDE MIRROR LH, ROCKER PANEL LH SIDE AND DAMAGE AREA	New	1,800.00
Gross Labour Cost (S\$)			5,530.00

Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM1522B80003 / Munich Autocare Pte Ltd
ENTRY DATE & TIME: 08/11/2022 13:48 (SGT)
SUBMITTED BY: Lim Jia Haw
VERSION: 1 (08/11/2022 13:48 (SGT))

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/11/2022 13:48 (SGT)
Reported by	Driver
Date of Accident	05/11/2022 14:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION OF UPPER CHANGI ROAD EAST & SIMEI RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMQ8827K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	BIS MOTORING PTE LTD
Company Reg No	2XXXXX055D
Email Address	KEIFTAN@BISMOTORING.COML.SG
Mobile Phone No	(Phone) +65-86881311
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Opel
Model	Astra
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Manual
CC	1600


INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2002451400

DRIVER

Name of Driver	WEE YUI KIM
NRIC No	SXXXX067I
Date Of Birth	10/02/1975
Occupation	Outdoor

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police Report T/20221105/2064.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	055D
Vehicle Details	
Vehicle No.:	SMQ8827K
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2022
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.6 TURBO DIESEL (A)
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	A2183359JR5X0219
Chassis No.:	W0VBD8EG5K8034981
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$21,847.00
Original Registration Date:	09 Dec 2019 P
First Registration Date:	09 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$22,586.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2029
PARF Rebate Amount:	\$16,939.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,728.00
COE Rebate Amount:	\$28,140.00
Total Rebate Amount:	\$45,079.00

The information contained herein is correct as at 08 Nov 2022

OK