

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: SP2002451400
 Vehicle Reg. No.: SMQ8827K
 Driver Age/Info:
 TP Injury Involved? YES
 Insured/Claimant: BIS MOTORING PTE LTD

Ref. No:
 Date of Loss: 05/11/2022
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: OPEL ASTRA ST, 1.6 D TURBO
 DIESEL (A)
 Vehicle Colour: RED
 Engine No: A2183359JR5X0219
 Odometer: 114780 KM

Vehicle Reg. Date: 09/12/2019

Chassis No: W0VBD8EG5K8034981

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 12 ✓

*NOT WHOLE
 RETURN BY PAINT
 EX \$2000*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

\$ 23,958.40

COST OF CLAIMS

	Amount
Parts	24,019.60
Miscellaneous Items	269.00
Labour	5,530.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	29,818.60
- Excess (S\$)	2,000.00
(S\$)	27,818.60
+ GST 7.00% (S\$)	1,947.30
Nett Amount (S\$)	29,765.90

This claim is handled by: LIM JIA HAW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2022)

Parts: 144 OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	39054067	*FRONT BONNET 1329	R1	0.00	*1,023.00 F
2	1	39032149	*FRONT BONNET HINGLE LH	D11	0.00	*32.00 F
3	1	39032150	*FRONT BONNET HINGLE RH	D11	0.00	*32.00 F
4	1	39041995	*FRONT DOOR WING MIRROR	R1	0.00	*98.40 F
5	1	39111554	*FRONT SIDE MIRROR LH 385	M3C/M	0.00	*303.00 F
6	1	39081894	*FRONT HEADLAMP LH 609	M3C/M	0.00	*665.60 F
7	1	13426393	*FRONT HEADLAMP LOWER BRACKET LH	R1	0.00	*65.00 F
8	1	39011390	*FRONT FENDER LH	R1	0.00	*442.00 F
9	1	39115547	*FRONT FENDER INNER SHIELD LH	R1	0.00	*76.80 F
10	1	13491088	*FRONT FENDER LAMP LH	R1	0.00	*45.00 F
11	1	39086891	*FRONT FENDER BRACKET 28	R1	0.00	*22.40 F
12	1	39052728	*FRONT BUMPER 1294	Buc/CM	0.00	*1,632.80 F
13	1	39086895	*FRONT BUMPER RENTAINER LH 31	D11	0.00	*31.20 F
14	1	13481997	*FRONT BUMPER FOG LAMP COVER 165	M11	0.00	*180.70 F
15	1	39098907	*FRONT BUMPER FOG LAMP LH	R1	0.00	*295.10 F
16	1	39160867	*FRONT DOOR LH 1600	R1	0.00	*1,508.00 F
17	1		*FRONT DOOR HINGLE UPP 151	R1	0.00	*146.00 F
18	1		*FRONT DOOR HINGLE LOW 151	R1	0.00	*146.00 F
19	1	39117456	*FRONT ROCKER PANEL MOLDING	R1	0.00	*1,327.00 F
20	1	39024544	*FRONT RIM LH	CM	0.00	*276.00 F
21	1	YQ00956280	*FRONT PRESURE SWITCH LH		0.00	*164.00 F
22	1	39163258	*ROOF CURTAIN AIRBAG LH 2716	Buc/R	0.00	*2,346.00 F
23	1	39023001	*FRONT SEAT AIR BAG 3560	R1	0.00	*2,346.00 F
24	1	39201592	*FRONT SEAT BELT LH 927	R1	0.00	*792.00 F
25	1	39201593	*FRONT SEAT BELT RH 927	R1	0.00	*792.00 F
26	1	39201587	*REAR SEAT BELT LH 787	R1	0.00	*601.00 F
27	1	39201587	*REAR SEAT BELT RH 787	R1	0.00	*601.00 F
28	1	39040242	*TRIM, REAR PILLAR LOWER RH	CM/L	0.00	*53.00 F
29	1	39040243	*TRIM, REAR PILLAR LOWER LH	CM	0.00	*53.00 F
30	1	39052732	*TRIM, REAR QUARTER UPPER RH	CM/L	0.00	*79.00 F
31	1	39052731	*TRIM, REAR QUARTER UPPER LH	CM	0.00	*79.00 F
32	1	39030299	*FRONT WHELL KNUCKLE ARM LH	R1	0.00	*520.00 F
33	1	13517459	*FRONT WHELL HUB 316	R1	0.00	*579.00 F
34	1	39089344	*FRONT WHELL LOWER ARM LH 350	R1	0.00	*619.00 F
35	1	39039573	*FRONT SHOCK ABSORBER LH	R1	0.00	*314.00 F
36	1	42705813	*FRONT STABILIZER BAR LINK 76	D11	0.00	*97.00 F
37	1		*FRONT TIE ROD LH 90	R1	0.00	*110.00 F
38	1		*FRONT TIE ROD RACK END LH 90	R1	0.00	*135.00 F
39	1	95522359	*FRONT DRIVER SHAFT 250	R1	0.00	*1,236.00 F
40	1	95529431	*FRONT STEERING RACK	R1	0.00	*1,972.00 F

F=Franchise part.

WPSH tank ad 91-00

Sub Total (\$\$)

21,836.00

+ Margin on L,N Items 10.00% (\$\$)

2,183.60

Total Parts (\$\$)

24,019.60

Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
-----	-----	----------	-------------	-------	-------	--------

Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	7	BUMPER CLIP	49.00
2	10	FENDER INNER SHIELD CLIP LH	70.00
3	1	FRONT TYRE LH	115.00
4	1	QUOTER GLASS SEALANT	35.00
Sub Total (S\$)			269.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER , FENDER LH , PILLAR LH , FRONT DOOR LH , SIDE MIRROR LH , ROCKER PANEL LH SIDE AND DAMAGE AREA	New	1,800.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
4	TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	380.00
5	TO CONDUCT 4 WHEEL ALIGNMENT AND BALANCING	New	120.00
6	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH AND FRONT SEAT CUSHION AIR BAG LH	New	380.00
7	TO REMOVE & INSTALL FRONT LH AND REAR LH SUSPENSION AND UNDERCARRIAGE CONTROL SYSTEM AND INCLUDING TO REPLACE DAMAGED PART	New	380.00
8	TO DISMANTLE ROOF LINING AND INSTALL ALL ELECTRICAL COMPARTMENTS , CONTROL UNITS AND SIDE COMPARTMENT TRIM BOARD TO REPLACE LEFT SIDE CUSHION AIR BAG	New	350.00
9	TO REMOVE & REFIX QUOTER GLASS	New	80.00
10	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , BONNET , BUMPER , FENDER LH , PILLAR LH , FRONT DOOR LH , SIDE MIRROR LH , ROCKER PANEL LH SIDE AND DAMAGE AREA	New	1,800.00
Gross Labour Cost (S\$)			5,530.00

Munich Autocare Pte Ltd/SMQ8827K/09/11/2022 10:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: