

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 09 Nov 2022

**Preliminary Advice**

|                    |                 |                         |                         |
|--------------------|-----------------|-------------------------|-------------------------|
| Vehicle No         | : SND7658U      | Accident Date           | : 03/11/2022            |
| Make               | : TOYOTA SIENTA | Policy No.              | :<br>DMHCSNW00002032200 |
| Assignment Date    | : 08/11/2022    | Excess                  | : S\$1,250.00           |
| Date of Inspection | : 9/11/2022     | Est. Duration of Repair | : 5                     |
| Inspection At      | :               |                         |                         |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,899.24 |
| Revised Amount              | :S\$ | 4,924.24 |
| Check Items (Estimated)     | :S\$ | 830.00   |
| Total                       | :S\$ | 5,754.24 |
| Lump Sum Repair             | :S\$ |          |

**Total Loss Consideration**

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 113,000.00 |
| Salvage Value      | :S\$ | 59,051.00  |
| Margin for Repair  | :S\$ | 53,949.00  |

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .