



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SJS6065E (MARVYN)**
Your Ref: **GBD136Y**

Date: **09-Nov-22**

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

Email : motor_claims@first-insurance.com.sg

First Capital Insurance Limited

6 Raffles Quay #21-00
Singapore 048580

Assessed Vehicle No : **SJS6065E**
Car Make and Model : **HYUNDAI HD AVANTE 1.6 A**
Date of Accident : **26-Oct-22**
Date of Assessment : **09-Nov-22**

We have carried out a physical assessment of SJS6065E at our workshop Auto Insure Pte Ltd
sustained damages to the REAR portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had
sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount	:	L/S	
Adjusted Amount	:	\$	9,124.02
Est. Repair Days	:	7	



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated
as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which
the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: **SJS6065E**

Your Ref: **GBD136Y**

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BOOTLID <i>lt /</i>		\$ 1,184.20
2	1	REAR BOOTLID HINGE LH <i>X</i>		\$ 134.70
3	1	REAR BOOTLID HINGE RH <i>X</i>		\$ 134.70
4	1	REAR BOOTLID LOCK <i>at /</i>		\$ 266.10
5	1	REAR BOOTLID LOGO <i>ne /</i>		\$ 94.80
6	1	REAR BOOTLID EMBLEM(AVANTE) <i>ne /</i>		\$ 88.90
7	1	REAR FENDER LH <i>repair</i>		\$ 1,852.50
8	1	REAR TAILLAMP OUTER LH <i>?</i>		\$ 491.70
9	1	REAR TAILLAMP INNER LH <i>sia /</i>		\$ 414.60
10	1	REAR TAILLAMP OUTER RH <i>X</i>		\$ 491.70
11	1	REAR TAILLAMP INNER RH <i>X</i>		\$ 414.60
12	1	REAR BUMPER <i>de /</i>		\$ 472.30
13	1	REAR BUMPER SIDE RETAINER RH <i>X</i>		W/BUMPER
14	1	REAR BUMPER SIDE RETAINER LH <i>X</i>		W/BUMPER
15	1	REAR BUMPER REINFORCEMENT <i>cra /</i>		\$ 482.20
16	1	REAR END PANEL <i>lt /</i>		\$ 583.40
17	1	REAR END PANEL INNER TRIM <i>?</i>		\$ 177.50
			SUB TOTAL	\$ 7,283.90
			LESS 20%	\$ 1,456.78
			TOTAL AMOUNT	\$ 5,827.12

Our Ref: **SJS6065E**

Your Ref: **GBD136Y**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS <i>ne /</i>		\$ <i>30</i> 50.00
2	1	REAR END PANEL SEALANT <i>ne /</i>		\$ <i>40</i> 60.00
3	1 SET	REAR PARKING SENSORS <i>AW /</i>		\$ <i>200</i> 250.00
			SUB TOTAL	\$ 360.00
			TOTAL PARTS COST	\$ 6,187.12

Our Ref: **SJS6065E**

Your Ref: **GBD136Y**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 600 ⁷⁰⁰ 1,000.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 30 100.00
3	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS	\$ 40 100.00
4	TO REMOVE & REFIX UPHOLSTERY GARNISH AND ATTACHMENT PARTS	\$ 60 120.00
5	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 800.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 40 50.00
7	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 20 50.00
8	TO VACUUM, WAXING & CLEAN	\$ X 60.00
9	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 20 50.00
TOTAL BEFORE GST		\$ 8,527.12
GST 7%		\$ 596.90
TOTAL (PARTS & LABOUR):		\$ 9,124.02

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 9,100.00 for LUMP SUM with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul

Hp 90010068

7 days

4/5

16/11/22 @ 1320

Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/10/2022 18:12 (SGT)
Reported by	Both
Date of Accident	26/10/2022 08:40 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TOWARDS TUAS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJS6065E

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ROZAIDI BIN ABDUL RAHIM
NRIC No	SXXXX679J
Email Address	LEELAROHIM82@GMAIL.COM
Mobile Phone No	(Phone) +65-89161934
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variant	1.6 A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/00959292/01

DRIVER

Name of Driver	ROZAIDI BIN ABDUL RAHIM
NRIC No	SXXXX679J
Date Of Birth	29/05/1980
Occupation	Outdoor

Date Of Driving Pass	07/05/2002
Driving experience	20 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-89161934
Alt. Phone Number	-
Email Address	LEELAROHIM82@GMAIL.COM
Address	BLK 230 PENDING ROAD #03-51
Address complement	-
Postcode	S670230
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	NA
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Panjang Neighbourhood Police Centre
Police Station Address	No.1 Segar Road #01-05 Singapore 677738
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN


ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD136Y
Vehicle Manufacturer	-

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20221026/2083

2 of 4

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20221026/2083

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YEO SIOW TONG	ID No.	S7243830B
Related Vehicle	GBD136Y (Van)	Contact No.	84919529
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ROZAIDI BIN ABDUL RAHIM	ID No.	S8015679J
Related Vehicle	SJS6065E (Car)	Contact No.	89161934
Hospital/Clinic	PROHEALTH 24-HOUR MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	26/10/2022	Date Discharge	26/10/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	LEELA BINTE ROHIM	ID No.	S8203791H
Related Vehicle	SJS6065E (Car)	Contact No.	96931791
Hospital/Clinic	PROHEALTH 24-HOUR MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	26/10/2022	Date Discharge	26/10/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 26th October 2022 at about 0840hrs, I was travelling in my vehicle (Black Hyundai Avante, SJS6065E) along PIE heading towards Tuas, near exit of Toh Guan Avenue. At the time, I was driving with wife, whom was seating at the front passenger seat of my car.

I was travelling on left most lane of the expressway, next to the road shoulder. The traffic flow was rather heavy at the time. The vehicle ahead of me had braked to slow down as the traffic ahead of it was slowing down. As such, I followed suit. While doing so, I felt a bump from my vehicle's rear. I realized that the vehicle (White Van, GBD136Y) at my rear had bumped and collided with my vehicle's rear. Subsequently,

**SINGAPORE
POLICE FORCE**

T/20221026/2083

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 4

Report No. T/20221026/2083

CONTINUATION OF REPORT

both drivers exited our vehicles to make further inspection on the damages to our vehicles.

Both drivers then exchanged particulars and took photos of the damages on hand. I could make out from the damages that the said vehicle right bumper had collided with my vehicle's left bumper. My vehicles suffered dents and scratches on it left bumper. The bumper had also come off slightly. Also, due to the accident, the rear boot was dented and had difficulty opening and closing. The other vehicle had sustained scratches and dents to its right side bumper.

My wife (Leela Binte Rohim, S8203791H) and I had suffered injuries from the accident. Due to the impact of the collision, I was forced forward and my right head had knocked onto the dashboard of my vehicle, which resulted in injury to my right shoulder. My wife however, sustained back strain when she was forced forward and landed back onto the car seat. Both my wife and I had visited the clinic the same day and was give 3 days of MC.

My vehicle had an in-built camera installed, however it was not working at the time. I affirm that are no damages to any government properties caused by the accident. I am unsure of the injuries which the other driver had sustain.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	
Owner ID:	Singapore NRIC
Vehicle Details	
	679J
Vehicle No.:	
Vehicle to be Exported:	SJS6065E
Intended Deregistration Date:	No
Vehicle Make:	09 Nov 2022
Vehicle Model:	HYUNDAI
Primary Colour:	HD AVANTE 1.6 A
Manufacturing Year:	Black
Engine No.:	2009
Chassis No.:	G4FC9U681073
Maximum Power Output:	KMH DU41BR9U802129
Open Market Value:	89.7 kW (120 bhp)
Original Registration Date:	\$11,224.00
First Registration Date:	26 Aug 2009
Transfer Count:	26 Aug 2009
Actual ARF Paid:	3
	\$4,276.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$29,328.00
COE Rebate Amount:	\$19,922.00
Total Rebate Amount:	\$19,922.00

The information contained herein is correct as at 09 Nov 2022

OK

Hyundai Avante 1.6A (COE till 03/2029)

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$53,800****Depreciation** ⓘ

\$8,500 /yr

Reg Date13-Mar-2009
(6yrs 3mths 27days COE left)**Mileage**

N.A.

Manufactured ⓘ

2009

Road Tax ⓘ

\$1,033 /yr

Transmission

Auto

Dereg Value ⓘ

\$16,161 as of today (change)

OMV ⓘ

\$11,943

COE ⓘ

\$25,525

ARF ⓘ

\$11,943

Engine Cap

1,591 cc

Power

89.7 kW (120 bhp)

Curb Weight ⓘ

1,264 kg

No. of Owners ⓘ

4

Type of Vehicle

Mid-Sized Sedan