



Section A - Accident Details

Registration Number	SHC4738T
Case Reference Number	TAX/11/22/2013
Registration Date	20/1/2015
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YIP YEW CHEONG
Type of Accident	Head To Side
Accident Date and Time	8/11/2022 5:30 PM
Accident Reported Date and Time	9/11/2022 12:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116820
Special Instruction to ARC, if any	LEFT REAR SIDE PORTION NEAR TYRE DENTED AND SCRATCHED
Prepared Date and Time	9/11/2022 1:46 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$1,879.10	\$23.52
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$3,991.10	\$823.52
Lump Sum Total	\$4,000.00	\$800.00 (L/S)
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang (LKK) / ERGO
ARC / Surveyor Sign Off Date	14/11/2022 4:20 PM	11/11/2022 5:15 PM
Signature		
Remarks	REQ NBV / LUMPSUM REPAIR / AFTER PAINT PHOTOS, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :quoqiang@lkkauto.com HP:82880282	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0026	Invoice Number	
Quotation Date	07.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY FUEL LID COVER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
Total Other Costs	\$500.00	\$0.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		90467-07211	BUMPER CLIPS (10 PCS)	0.00	\$2.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$108.70	0.00	\$0.00	Replace	Not Given
		52592-47021	BUMPER SEAL, RR LH	0.00	\$101.80	0.00	\$0.00	Replace	Not Given
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given
		61602-47091	FENDER RR/LH	1.00	\$980.80	100.00	\$0.00	Replace	Repair
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		65638-47021	FENDER LINER R/LH	0.00	\$159.80	0.00	\$0.00	Replace	Not Given
		52563-47010	TAIL LAMP BRACKET, LH	0.00	\$35.20	0.00	\$0.00	Replace	Not Given
		81561-47170	TAIL LAMP LH	0.00	\$618.60	0.00	\$0.00	Replace	Not Given
		77350-47030	LID ASSY, FUEL	0.00	\$116.80	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
R
√
√
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/12/2022

User ID : PohSuan

			STICKER PETROL ONLY	0.00	\$7.80	0.00	\$0.00	Replace	Not Given
Total					\$2,914.10		\$29.40		

X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	29.40	
	-20%	
	23.52	L/S \$800/-
+	400.00	
+	400.00	
	823.52	