

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 12/12/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHF385M
Case Reference Number	TAX/11/22/2011
Registration Date	26/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	KAMARUDIN BIN YUSOPE
Type of Accident	Side Swipe
Accident Date and Time	8/11/2022 8:35 PM
Accident Reported Date and Time	9/11/2022 10:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116819
Special Instruction to ARC, if any	TP/ RIGHT FRONT PORTION /INCOME
Prepared Date and Time	9/11/2022 1:59 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$11,120.12	\$3,238.95
Total Other Cost	\$380.00	(\$788.95)
TOTAL COST	\$13,112.12	\$3,050.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	09/11/2022 3:52 PM	09/11/2022 3:16 PM
Signature		
Remarks	LUMPSUM REPAIR / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0011	Invoice Number	
Quotation Date	06.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$788.95)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	(\$788.95)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	Replace
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		52127-47911	COVER, FR BUMPER RH	1.00	\$32.70	25.00	\$24.53	Replace	Replace
		53395-47060	SEAL, HOOD TO FR END	0.00	\$92.40	0.00	\$0.00	Replace	Not Given
		53112-47310	GRILLE, RADIATOR	0.00	\$192.80	0.00	\$0.00	Replace	Not Given
		53101-47100	GRILLE SUB-ASSY	0.00	\$457.10	0.00	\$0.00	Replace	Check
		53111-47140	GRILLE, SUB -ASSY , 2	0.00	\$170.20	0.00	\$0.00	Replace	Not Given
		51451-12120	COVER ASSY, ENGINE	0.00	\$261.60	0.00	\$0.00	Replace	Not Given
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52535-50060	RETAINER, FR BUMPER, LH & RH	0.00	\$9.50	0.00	\$0.00	Replace	Not Given
		52421-47030	PAD, FRONT BUMPER (NO.1)	0.00	\$44.10	0.00	\$0.00	Replace	Not Given
		52421-47040	PAD, FRONT BUMPER (NO.2)	0.00	\$38.90	0.00	\$0.00	Replace	Not Given
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$103.70	25.00	\$77.78	Replace	Replace

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 12/12/2022

User ID : PohSuan

		52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
		52611-47210	ABSORBER, FR BUMPER	1.00	\$86.60	25.00	\$64.95	Replace	Replace	√
		52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given	X
		52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given	X
		52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$265.90	0.00	\$0.00	Replace	Not Given	X
		52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$773.90	0.00	\$0.00	Replace	Check	X
		81145-47890	UNIT , HEADLAMP , RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace	√
		81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$4,079.80	0.00	\$0.00	Replace	Not Given	X
		81210-12240	LAMP ASSY, FOG, RH	0.00	\$256.50	0.00	\$0.00	Replace	Not Given	X
		81935-47070	CORD, FOG LAMP	0.00	\$60.60	0.00	\$0.00	Replace	Not Given	X
		51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$511.20	0.00	\$0.00	Replace	Not Given	X
		51443-12110	COVER, ENGINE UNDER SIDE RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
		53205-47900	SUPPORT S/A UPPER,	0.00	\$408.50	0.00	\$0.00	Replace	Not Given	X
		53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
		53801-47080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair	R
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		53875-47120	LINER, FR FENDER, RH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given	X
		53851-47061	PAD, FR WHEEL RH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
Total					\$13,333.70		\$3,238.95			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	3,238.95	
+	200.00	L/S \$3,050/-
+	400.00	
	3,838.95	
	-20%	
	3,071.16	